



Installation Technology Transition Program (ITTP)

ROOFER Inventory Procedures and Inspection Manual for Metal Panel Roofing

David M. Bailey, Joseph E. Karbarz, and Katharine E. Sweeton

December 2012



The US Army Engineer Research and Development Center (ERDC) solves the nation's toughest engineering and environmental challenges. ERDC develops innovative solutions in civil and military engineering, geospatial sciences, water resources, and environmental sciences for the Army, the Department of Defense, civilian agencies, and our nation's public good. Find out more at www.erdc.usace.army.mil.

To search for other technical reports published by ERDC, visit the ERDC online library at http://acwc.sdp.sirsi.net/client/default.

ROOFER Inventory Procedures and Inspection Manual for Metal Panel Roofing

David M. Bailey

Construction Engineering Research Laboratory US Army Engineer Research and Development Center 2902 Newmark Drive Champaign, IL 61822

Joseph E. Karbarz

Information Technology Laboratory
US Army Engineer Research and Development Center
3909 Halls Ferry Road
Vicksburg, MS 39180-6199

Katharine E. Sweeton

US Army Engineer District, Louisville 600 Dr. M L King Jr Place Louisville, KY 40202-0059

Final report

Approved for public release; distribution is unlimited.

Prepared for Office of the Assistant Chief of Staff for Installation Management (ACSIM)

Arlington, VA 22202

Under Project FY10-04, "ROOFER Condition Assessment Procedures for Metal

Roofing"

Abstract

The US Army is responsible for maintaining millions of square feet of metal panel roofing on a wide variety of facilities. This type of roofing system shares a number of general characteristics with other types, but they use certain distinct types of materials that have their own specialized distress and degradation mechanisms.

Dedicated inspection guidance and condition index calculation methods are needed to quantify the condition of an installation's metal panel roofing assets in order to make the best use of Army maintenance and repair resources. This manual was developed to serve as a standard reference for performing inspections and calculating a flashing condition index (FCI) and panel condition index (PCI) for use in facility maintenance management activities. This guidance represents a new implementation of the widely used ROOFER Sustainment Management System.

DISCLAIMER: The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official endorsement or approval of the use of such commercial products. All product names and trademarks cited are the property of their respective owners. The findings of this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

DESTROY THIS REPORT WHEN NO LONGER NEEDED. DO NOT RETURN IT TO THE ORIGINATOR.

Contents

Ab	stract	i
Fig	gures	iv
Pre	eface	v
Un	it Conversion Factors	vi
1	Introduction	1
	Background	1
	Objective	
	Approach	
	Using this manual	2
	Mode of technology transfer	2
2	Metal Roofing Inventory Procedures	3
	Metal panel roofing system categorization	3
	Separate cap	4
	Integral cap	5
	Mechanically interlocked	6
	Lap seam	7
	Roof network identification	7
	Building	7
	Roof sections	8
	Data collection	8
	Building identification sheet	9
	Roof section identification worksheet	9
	Roof section identification sheet	
	Roof inspection worksheet	
	Calculating roof section area	12
3	Metal Roofing Inspection Procedures	21
	Inspection team	
	Supplies	22
	General inspection guidelines	22
	Survey preparation	23
	Roof section plan validation	23
	Determining total length of flashed perimeter and curb flashings	23
	Determining total number of through-panel fasteners	24
	Distress survey	24
	Determining the FCI and PCI	25

4	Flashing Distresses	26
	Flashing Fastener (FF)	26
	Localized Flashing Surface Deterioration (FD)	28
	Panel Closure (PC)	
	Eave Flashing (EA)	33
	Rake Edge Flashing (RE)	36
	Ridge Cap, Hip Cap (CP)	39
	Valley Flashing (VF)	42
	Headwall Transition Flashing (HT)	45
	Sidewall Transition Flashing (ST)	
	Continuous Roof-to-Wall Panel Transition Flashing (RW)	50
	Built-in Gutters (IG)	
	Flexible Boot Flashings (FB)	54
	Flanged Metal and Raised Curb Flashing (FM)	57
	Ancillary Flashing (AF)	
	Flashing Patch (FR)	
5	Metal Panel Distresses	67
	Section-Wide Surface Deterioration (SW)	
	Localized Surface Deterioration (SD)	
	Panel Fastener Defect (PF)	
	Damaged Panel (DP)	
	Displaced Panel (DL)	
	Panel Patch (PA)	
	Debris and Vegetation (DV)	
	Improper Equipment Supports (EQ)	
	Mechanically Interlocked Seam Defect (MS)	
	Integral Cap Seam Defect (IC)	
	Separate Cap Seam Defect (SC)	
	Lap Seam Defect (LS)	
	Transverse Panel Lap Defect (PL)	
	Integrated Skylight Panel Defect (SP)	
Ref	ferences	93
Apı	pendix A: Deduct Value Curves	94
	pendix B: Condition Index Calculation Methodology	
	·	
Apı	pendix C: Blank Worksheets	116
Rei	nort Documentation Page	

ERDC TR-12-15 iv

Figures

Figure 1. Snap-cap seam (source: NRCA)	5
Figure 2. Traditional batten seam (source: NRCA)	5
Figure 3. Snap-on batten cap with clip (source: NRCA)	5
Figure 4. Capped standing seam (source: NRCA)	5
Figure 5. Snap-lock seam (source: NRCA)	6
Figure 6. Mechanically seamed single-lock seam (source: NRCA)	6
Figure 7. Mechanically seamed double-lock seam (source: NRCA)	6
Figure 8. Trapezoidal seam (source: NRCA)	6
Figure 9. Raised lap seam (source: NRCA)	7
Figure 10. R-panel seam	7
Figure 11. Flat lap seam (source: NRCA)	7
Figure 12. Building Identification Worksheet with sample data	13
Figure 13. Roof Section Identification Worksheet (page 1) with sample data	14
Figure 14. Roof Section Identification Worksheet (page 2) with sample data	15
Figure 15. Roof Section Identification Worksheet (page 3) with sample data	16
Figure 16. Roof Section Identification Sheet with sample data	17
Figure 17. Roof Inspection Worksheet with roof section plan	18
Figure 18. Standard symbols for roof section plan	19
Figure 19. Roof Inspection Worksheet with inspection data	20

Preface

This study was conducted for the Office of the Assistant Chief of Staff for Installation Management (OACSIM) under the Installation Technology Transition Program (ITTP); Project FY10-04, "ROOFER Condition Assessment Procedures for Metal Roofing." The ITTP Program Manager was Debbie J. Lawrence, CEERD-CV-T, and the Technical Monitor was Philip R. Columbus, DAIM-ODF.

The work was performed by the Materials and Structures Branch (CF-M) of the Facilities Division (CF), US Army Engineer Research and Development Center, Construction Engineering Research Laboratory (ERDC-CERL). At the time of publication, Vicki L. Van Blaricum was Chief, CEERD-CF-M; L. Michael Golish was Chief, CEERD-CF; and Martin J. Savoie was the Technical Director for Installations. The Deputy Director of ERDC-CERL was Dr. Kirankumar Topudurti and the Director was Dr. Ilker Adiguzel.

The illustrations of seam details in Chapter 2 and illustrations of the flashing details in Chapter 4 are adapted from the *NRCA Roofing Manual: Metal Panel and SPF Roof Systems* – *2012*, with the permission of the National Roofing Contractor Association (NRCA).

Special acknowledgement is given to following individuals, who were key members of the development team and participated in all field testing and validation efforts:

- Mark deOgburn, Naval Facilities Engineering Command (NAVFAC)
- Tim Benzie, Inspec, Inc., Minneapolis, MN
- Dane Bradford, Bradford Roof Management, Billings, MT
- Mike Quinn, Conley Group Inc., Irving, TX.

COL Kevin J. Wilson was the Commander of ERDC, and Dr. Jeffery P. Holland was the Director.

ERDC TR-12-15 vi

Unit Conversion Factors

Multiply	Ву	To Obtain
feet	0.3048	meters
inches	0.0254	meters
mils	0.0254	millimeters
pounds (mass)	0.45359237	kilograms
square feet	0.09290304	square meters
square inches	6.4516 E-04	square meters
square yards	0.8361274	square meters
yards	0.9144	meters

1 Introduction

Background

The US Army Engineer Research and Development Center, Construction Engineering Research Laboratory (ERDC-CERL) has developed the ROOFER Sustainment Management System (SMS) for low-slope membrane and asphalt shingle roofs. The ROOFER SMS provides installations with standardized procedures for performing the inventory, inspection, condition assessment, and network and project analyses for managing their roof assets and making decisions on repair and replacement requirements. ERDC-CERL also developed Micro ROOFER (Bailey 2003), to an automated tool for performing asset management using ROOFER procedures and collected roof asset data. Recently, ERDC-CERL completed a conversion of that tool to a web-based application.

Using procedures that were developed for bituminous built-up (Shahin, Bailey, and Brotherson 1987b), modified bitumen (Bailey 2010), single-ply membrane (Bailey et al. 1993), and asphalt shingle roofs (Bailey 1999), most of the roofing systems used on Army installations can now be inspected and managed using the ROOFER SMS. Metal roofing, the remaining roof type that comprises a significant portion of the Army's roofing assets, had not been addressed before now. Many ROOFER user requests have indicated the need for a procedure to assess metal panel roofs.

Objective

The objective of this work was to develop ROOFER inventory, inspection, and condition index procedures based on visual inspection of the metal panels and flashing components of metal panel roofing systems. This report provides roof inspectors with a standard reference for collecting physical and historical roofing system data, conducting inspections, and calculating the flashing condition index (FCI) and panel condition index (PCI) for metal panel systems.

Approach

The concepts and theory behind the ROOFER condition indexing methodology, and the process used to develop and field-validate the distress definitions and deduct value curves, were documented in Shahin, Bailey, and

Brotherson (1987a). The developmental process for metal systems included technical contributions by a rating team of experts and field tests at several sites (military and nonmilitary).

Using this manual

Chapter 2 contains the inventory procedure for metal roofing systems. Chapter 3 provides the inspection procedures for metal panel roofing systems only. The inspection procedures are not applicable to metal shingle panel, flat-locked seam panel, or other hybrid systems that are not as commonly used today. Distresses for flashings and panels are presented in Chapters 4 and 5, respectively. Those two chapters include descriptions of distresses, severity levels, defect definitions, photographs, and measurement criteria. Inspectors should study this manual and carry a copy for reference during inspections.

The inspection procedures require technically qualified determinations related to distress severity and the need to replace failing panels. Therefore, the inspection team should include at least one individual having experience with and technical knowledge of metal panel roofing systems.

Results of roof inspections are to be used in conjunction with the calculation procedures provided in Appendix B, "Condition Index Calculation Methodology," to determine the FCIs and PCIs. Deduct value curves used in the calculations are presented in Appendix A. Appendix C includes blank specimens of both the ROOFER inventory and inspection worksheet, and other forms, which may be photocopied for use in the field.

Mode of technology transfer

Information about the ROOFER SMS and support are available at the US Army Engineer Research and Development Center online fact sheet navigation page:

http://sms.cecer.army.mil/SitePages/ROOFER.aspx

Inquiries about ROOFER may be directed to Chief, Materials and Structures Branch (CEERD-CF-M), US Army Engineer Research and Development Center, Construction Engineering Research Laboratory (ERDC-CERL), PO Box 9005, Champaign, IL 61826-9005, 217-352-6511.

2 Metal Roofing Inventory Procedures

The roofing inventory is the foundation of ROOFER. It provides the information needed by engineering personnel to manage their roofing assets. Well maintained inventory data, when combined with inspection data (discussed in Chapters 3, 4, and 5), will provide a construction history of each roof, identification of problems that require repair, and a performance record that can be used to determine repair and replacement strategies.

This chapter presents the inventory procedures for metal roofing systems. Two sets of inventory procedures were previously developed for the ROOFER SMS — one for low-slope membrane roofs (Bailey 1990) and another for steep roofs (Bailey 1999). Before development of the procedures presented here, metal roofs were inventoried using the procedures for steep roofs.

Metal panel roofing system categorization

The inspection procedures presented in this report are used to evaluate the more common metal panel systems. They do not apply to metal shingle panel, flat-locked seam panel, or other hybrid metal roofing systems, which are not used in high numbers today on military installations.

To be able to inspect and assess the condition of metal panel roofing systems, it was necessary to develop a standardized method for classifying the many different systems that are available. There are many ways of categorizing metal panel roofing systems. One common method classifies metal roof systems as being either hydrokinetic (water-shedding) or hydrostatic (waterproof). Hydrokinetic systems provide watertightness by applying slope and gravity. These systems are designed and installed to eliminate the potential for ponding and quickly shed water from the roof. With hydrostatic systems, the panel seams and other joinery between components and at junctures are designed and installed to be able to tolerate minimal hydrostatic pressure without leaking. These systems often rely on greater seam heights and more extensive use of sealants to prevent water penetration than do hydrokinetic systems.

Metal panel systems may also be categorized as architectural or structural. Architectural systems are usually installed over a solid or closely spaced substrate. They are typically hydrokinetic systems, and their supporting substrates are covered with waterproof underlayments that provide additional protection. Architectural metal systems are used on steep slopes, so they contribute significantly to the visual appearance of the building façade. Structural metal systems do not require the support of a solid substrate; the panels can span framing members, which for most systems are spaced at 5 foot intervals. These systems are most often hydrostatic, and can be used on low-slope applications. It should be noted, however, that the terminology used in metal panel marketing literature may not be consistent with the descriptions offered here. Some systems marketed as architectural may be designed to span purlins, and some systems marketed as structural may be specified for fastening onto a structural deck.

Another basis for categorizing metal panel roofing systems is the method used to fasten and secure the panels to the substructure. For a concealed fastener system, primary attachment is achieved by using concealed clips integrated with the panel seams and fastened to the structure or substrate below. With a through-fastener system, the fasteners are placed through the panel and fastened to the structural system below, requiring a means of making the fastener hole watertight.

The type of seam used for joining adjacent panels is another characteristic that differentiates metal panel roofing systems. For the ROOFER inventory procedure, a simplified method for categorizing seams is most useful. Four panel seam types are used: *separate cap, integral cap, mechanically interlocked*, and *lap*. The first three types are used primarily with concealed fastener systems while the lap seam is typically used on throughfastener metal panel systems.

Separate cap

For separate cap seams, panel joinery is accomplished with a separate cover. Variations of this seam type include a snap cap (Figure 1), batten cover (Figure 2 and Figure 3) and capped standing seam (Figure 4). These systems use concealed clips as their primary method of attachment.



Figure 1. Snap-cap seam (source: NRCA)




Figure 2. Traditional batten seam (source: NRCA)




Figure 3. Snap-on batten cap with clip (source: NRCA)



Figure 4. Capped standing seam (source: NRCA)

Integral cap

Integral cap seams join panels by using a seam cover integrated into one of two adjoining panels. Typically the seam has a "snap-lock" configuration (Figure 5). These systems use concealed clips as their primary method of attachment.




Figure 5. Snap-lock seam (source: NRCA)

Mechanically interlocked

Mechanically interlocked seams join panels by mating the legs of two adjacent panels and bending or folding. The seaming is typically performed by hand or automated equipment. Figure 6 depicts a single-lock seam that has a fold of 90 degrees. Figures 7 and 8 depict double-lock seams that have 180 degree folds. Mechanically interlocked seam systems use concealed clips as their primary method of attachment.



Figure 6. Mechanically seamed single-lock seam (source: NRCA)




Figure 7. Mechanically seamed double-lock seam (source: NRCA)




Figure 8. Trapezoidal seam (source: NRCA)

Lap seam

Lap seam systems use through fasteners as their primary method of attachment. Panels are joined by simply overlapping adjacent panels and securing them to the substrate with fasteners that penetrate the panels (Figure 9, Figure 10, and Figure 11).




Figure 9. Raised lap seam (source: NRCA)




Figure 10. R-panel seam




Figure 11. Flat lap seam (source: NRCA)

Roof network identification

A roof network, as defined within the ROOFER system, consists of all the building roofs maintained by an installation or facility manager. A network is generally divided into the following manageable components:

Building

A building consists of one distinct structure that may include several wings or sections, but generally has one building number or designation. Buildings connected by covered walks or enclosed passageways should be considered separately unless they are designated by the same building num-

ber. Facility complexes with only one building number or designation should be given sub-designations for easier identification.

Roof sections

Building roofs are managed by units called *roof sections* for which all repair and replacement decisions can be made. To achieve this, each roof section is inspected and evaluated independently of other roof sections. As a rule, a building having a single roofing system type that was all installed at the same time and measuring less than approximately 10,000 square feet should be managed as one section. Roofing on dormers and similar projections should be included with the main roof section. For buildings with larger roof areas, the roof may be divided into two or more sections. For those buildings, the inspector should inspect and rate each section independently. Using this approach, a roof section in poor condition does not detract from the assessment of a roof section on the same building that is performing well. Also, it may be possible to replace only those sections that have reached the end of their service life while making necessary repairs to the remaining sections.

Roof sections are assigned letter designations (A, B, C, etc.). For building roofs requiring multiple sections, the sections are generally delineated by:

- different weather exposure (e.g., north side and south side of a gabled roof)
- perimeter details such as firewalls, expansion joints, valleys, hips, or ridges
- different roof slopes or levels
- areas having different roof covering types, different amounts of rooftop equipment, or significantly different conditions below the roof
- areas that were constructed at different times.

If a roof is physically divided into many small areas, strong consideration should be given to combining these areas with a larger adjacent roof area to comprise one roof section.

Data collection

The information needed to successfully manage a roof network must be stored in a way that makes the data accessible and usable. The data collection system described in this report allows easy input into the web-based

ROOFER application. Once a database is established, a facility manager can perform analyses and develop reports that are needed to effectively manage large networks of building roofs or individual roof projects.

The physical and historical information about buildings and roof sections are recorded on standardized forms. The information can come from a variety of sources. At installations that have complete building records, most of the data can be taken from as-built drawings, record drawings, and specifications. Because these drawings and specifications often do not show actual conditions, all the data should be verified during the visual inspection.

It is important that the collected information be as complete as possible. Missing data will make analysis and planning difficult. Although this phase does require some investment of time and effort, it needs to be done only once and then updated when a roof system is modified.

Building identification sheet

The *Building Identification Sheet* (Figure 12) provides general information that includes building name, number, location, occupancy, and the date of original construction of the building. It also lists each roof section and its area. A space is also provided on the sheet for placing a building roof plan that shows overall dimensions and identifies each roof section. The plan should be drawn to a scale that will fully utilize the space available on the sheet. For large buildings, a scale of 1 in. = 30 ft or 1 in. = 60 ft will probably be necessary to show the entire roof.

Roof section identification worksheet

The three-page *Roof Section Identification Worksheet* (Figures 13, 14, and 15) simplifies the task of collecting the inventory data for a metal roof section and ensures uniformity in reporting terminology. Most of the items are self-explanatory, and the collection process uses checklists for identifying the various system components. Data can be obtained from specifications, drawings, and visual inspection.

The worksheet has a header section and additional sections for seven categories: 10 – General; 20 - Structural Frame; 30 - Roof Deck; 40 – Underlayment; 50 – Roof Covering; 60 – Flashings; and 70 – Remarks. Descriptions of the collected inventory data follow:

10-General

Section 11 - Type. Slope configurations for the roofing system.

Section 12 - Access. The method used to gain access to the roof section. Note whether the ladder is inside or outside the building and if it is permanently attached to the building. If it is not, a portable ladder may be necessary for inspection. If access is from an adjacent roof section, identify the section.

20-Structural Frame

Section 21 - Type. The structural framing system that supports the roof.

30-Roof Deck

Section 31 – Structural Deck. The roof deck construction supporting the roof covering.

Section 32 — Attachment Surface. For roof coverings that are not attached directly to the structural deck, the intermediate structure or substrate to which attachment is made.

Section 33 - Slope. The predominant slope of the roof section. Slopes are to be recorded in 1/8 inch increments up to a slope of 1 inch per foot. For slopes greater than 1 inch per foot, the slopes are to be recorded in ½ inch increments. The roof plan will generally indicate the slope (e.g., 4 inches in 12). If the slope is not noted on the roof plan, the section drawings may indicate the slope. If such information is not available, field measurement will be required.

Section 34 - Drainage. The existing means of removing rainwater from the roof section. ROOF EDGE should be selected if the roof water flows over the building edge without gutters or scuppers to the ground or to a lower roof area. Check the roof section for gutters, downspouts, and interior drains.

40-Underlayment

Section 41 - Type. Any material course placed beneath the roof covering to provide additional protection to the deck, shed water, and provide a secondary weather protection.

50-Roof Covering

Section 51 - Type. The type of metal panel roofing system. It is necessary to categorize standing seam panel systems by the seam type.

Section 52 – Base Metal. The base metal of the roofing panel and any metallurgical coating.

Section 53 – Panel Finish. The type of polymeric coating added to the exposed surface of the metal panels.

Section 54 – Panel Attachment. The method used for attachment of the metal panels to the substrate.

60-Flashings

Section 61 - Type. Measure and record total amount of the various existing flashing details (i.e. eave, rake, ridge, hip, valley, headwall transition etc). For reference purposes, see the description sections and detail illustrations of the various flashing distresses in Chapter 4. Check the Roof Inspection Worksheet to ensure that all of the existing flashing, including penetrations, pitch pans, and pipe supports are shown and/or labeled on the roof section plan (see Figure 17).

Section 62 - Accessories. Types of roof accessories on the roof surface.

Section 63 - Overlay. Underlying layers of previous roofing systems.

70-Remarks

Additional information that will be useful to inspectors or facility managers.

Roof section identification sheet

The inventory data for a roof section can be entered directly into a computerized database using the web-based ROOFER application or compiled onto a *Roof Section Identification Sheet* (Figure 16).

Roof inspection worksheet

Each roof section should have a roof plan drawn to a scale that fits on the *Roof Inspection Workshee*t (Figure 17). The plan should show all physical roof features using the standard symbols and acronyms that are depicted on Figure 18. Locations of all termination flashings (i.e. eave, rake, ridge cap / hip cap) are to be indicated on the roof section plan using leader lines and the appropriate acronyms. Note that the total lengths of each of the types of termination flashings are to be recorded in section 61 of the *Roof Section Identification Worksheet*. Once completed, a master *Roof Inspection Worksheet* with a roof section plan can be scanned and saved in a JPEG digital image format and uploaded to the web-based ROOFER database. A copy can then be printed for use when performing future inspections.

Calculating roof section area

The roof section area that is required as part of the condition rating procedure should represent actual exposed surface area, not just the projected horizontal area. When measuring in the field, lengths taken in the plane of the roof slope should be used when calculating roof area. When dimensions are taken from aerial photographs, horizontal dimensions must be converted from the scaled measurements, and any linear dimensions that represent sloped surfaces need to be adjusted for length in the plane of the slope.

*			
BUILDING IDENTIFICA	TION SHEET	AGENCY / INST. NO.	:
DATE://	AGENCY / INST.:	100 III III	
BUILDING NAME: HCC			
BUILDING NUMBER: 700	DESIGN CATEGORY CO	ODE:	
TYPE CONST.: P	FACILITY NUMBER:		
LOCATION:		_	
USE:		YEAR BUILT:	
ROOF SECTIONS:			
B 11,990 SF G C 660 SF H D 640 SF I E 784 SF J	114 SF 114 SF 149 SF 126 SF 123 SF	K 113 SF L 55 SF M SF N SF O SF	Q SF R SF S SF
REMARKS:			
	71		
K[C	AHI	
J	В		E
D		FG	N N
BUILDIN	G ROOF PLAN		SCALE:

Figure 12. Building Identification Worksheet with sample data.

ROOF SECTION IDENTIFICATI	ON WORKSHEET AGENCY/I	NST.:
DATE: JUNG 20/2 BLDG. NO.	:625 SECTION ID: A	AREA: 12,400 SF
OCCUPANCY: OFFICE	YEAR ORIG. CONST.:	YEAR LAST REPLACED: 2007
10 GENERAL		
11 TYPE (check all):	GAMBREL SHED DOME	BARREL RADIUS PANEL OTHER
12 ACCESS (check one):		
INTERNAL LADDER Permanent Temporary	EXTERNAL LADDER Permanent Temporary	PENTHOUSE ACCESSED FROM ADJ. SECTION (Sec.ID) OTHER
20 STRUCTURAL FRAME		
21 TYPE (check one):		
STEEL Beams, Girders, Cols Long Sp Deck, Beams Trusses Bar Joists with Beams & Cols. Bar Joists with Bearing Walls Bar Joists with Combination	CONCRETE Beams Flat Slab WOOD Laminated Beams Trusses Joists Panels	SPECIAL Dome Space Frame OTHER UNKNOWN
30 ROOF DECK	1 7 - 1	
31 STRUCTURAL DECK (check of	one):	
NONCOMBUSTIBLE X STEEL	COMBUSTIBLE	
CONCRETE, STD Precast	WOOD BOARDS PLYWOOD	OTHER UNKNOWN
Cast-in-Place GYPSUM, PRECAST	WOOD FIBER	NONE
CONCRETE, LWT. PRECAST CEMENT FIBER Bulb-Tees Clipped		

Figure 13. Roof Section Identification Worksheet (page 1) with sample data.

32	ATTACHMENT SURFACE (if applica	able):	
	Planks Boards	WOOD FRAMING METAL PURLINS	OTHER UNKNOWN
33	SLOPE (primary): 2 IN 12 thereafter)	(1/8" increments up to 1";	34" increments
34	▼ GUTTERS &	& DOWNSPOUTS	INTERIOR GUTTERS INTERIOR DRAINS OTHER
40	UNDERLAYMENT		
41	X INTENDENT	ASPHALT SATURATED SHEET HIGH PERFORMANCE NON-ASPHALT SLIP SHEET	OTHER NONE
50	ROOF COVERING		
51	TYPE (check one): METAL PANEL - STANDING SEAM SEPARATE CAP Snap-on Batten T-Style MECHANICALLY INTERLOCKED Double lock seam Single lock seam INTEGRAL CAP Snap lock Integral batten	METAL PANE FLAT SOLDE METAL PANE OTHER	CRED SEAM

Figure 14. Roof Section Identification Worksheet (page 2) with sample data.

52	BASE METAL:	
	ZINC COATED STEEL TERNE (galvanized) COPPER ZINC-ALUMINUM STAINLESS STEEL COATED STEEL ZINC STEEL ALUMINUM	LEAD LEAD COATED COPPER UNKNOWN
53	PANEL FINISH:	1
	FACTORY APPLIED SMOOTH FACTORY APPLIED STONE COATED MAINTENANCE COATING OTHER NONE UNKNOWN	
54	PANEL ATTACHMENT: CONCEALED CLIPS OTHER EXPOSED FASTENERS IN PANELS	
60	FLASHINGS	
61	TYPES (Record lineal feet of each): 400 EAVE 24 RAKE EDGE CONTINUOUS ROOF TO WALL TRANSITION HIP CAP VALLEY HEADWALL TRANS. SIDEWALL TRANS. FLANGED METAL	RAISED CURB PITCH PANS
62	ACCESSORIES (check all): SNOW GUARDS WALKWAYS PHOTOVOLTAICS	LIGHTNING PROTECTION
63	OVERLAY:	
	IS ROOF OVERLAYED // (Y/N/UNKNOWN) # OF LAYERS	
70	REMARKS	
10	Riage vents , itegrated skylight Panels	

Figure 15. Roof Section Identification Worksheet (page 3) with sample data.

ROOF SECTION IDENTIFICATION		AGENCY/INST.:				
DATE: 54N/ 2012	BLDG	NO: 625	SE	CTION ID: A	AREA: 12,400 SF	
OCCUPANCY: OFFICE YEAR ORIG.		G.	CONST.:	YEAR LAST REPLACED: 7007		
10 GENERAL						
11 TYPE: GABLE						
12 ACCESS: EXTERN	JAL	LADDER	*.	TEMPORAF	27	
20 STRUCTURAL FRAME						
21 TYPE: BAR JO	ISTS	WITH E	3 E	ARING WA	LLS	
30 ROOF DECK	1					
31 STRUCTURAL DECK: {	STEE	EL				
METAL PURI		33 SLOPE		Z IN 12	34 DRAINAGE: ROGF EDGE GUTTERS & DOWNSPOUTS	
40 UNDERLAYMENT						
41 TYPE: UNKOW	N					
50 ROOF COVERING						
					ECH. INTERLOCKED - Single	
52 BASE METAL: ZINC						
53 PANEL FINISH: FA						
54 PANEL ATTACHMENT: 60 FLASHINGS	CON	CENTE)	CLIPS		
		60 30000		770.	50 011111111 W/W/INVENTOR	
61 TYPES: 400' EAVE 124' RARE 200' RIDGE	EDGE	62 ACCES.	-	-	63 OVERLAY: Y/N/UNKNOWN # OF LAYERS	
70 REMARKS:						
RIDGE VENTS INTEGRATED SKYLIGHT PANES						

Figure 16. Roof Section Identification Sheet with sample data.




Figure 17. Roof Inspection Worksheet with roof section plan.




Figure 18. Standard symbols for roof section plan.




Figure 19. Roof Inspection Worksheet with inspection data.

3 Metal Roofing Inspection Procedures

The inspection procedures presented in this chapter are based on the same concepts and theories used previously in developing the ROOFER inspection procedures for other roofing systems (Shahin, Bailey, and Brotherson 1987a, 1987b; Bailey et al. 1993). As with those systems, the roof covering component (metal panels) and flashing system component are assessed separately based on data collected during a visual distress survey.

For each roof section, a Panel Condition Index (PCI) and a Flashing Condition Index (FCI) are determined using the survey data and the calculation methodology described in Appendix B. The PCI and FCI are numerical values that range from 0-100, where 100 means excellent. For both the panel and the flashing, the index represents the roofing component's (1) ability to perform its functions, (2) needed level of maintenance and, (3) waterproof integrity.

The distress survey consists of identifying problems and characterizing them by distress type, severity level (high, medium, low), defect type, and quantity. Definitions and measurement techniques for the flashing distresses are presented in Chapter 4 and for the panel distresses in Chapter 5. A thorough visual inspection must be conducted in strict accordance with these two chapters, using the procedures defined below to ensure that meaningful and valid condition assessment is achieved. The inspection must be carefully organized and planned.

This chapter presents inspection procedures to be used in conducting the visual distress survey for metal panel roofing systems.

Inspection team

A team of at least two people—an inspector and a recorder—should perform the roof inspection. The inspection procedures require technically qualified determinations related to distress severity and the need to replace failing panels. Therefore, the inspection team should include at least one member having experience with and technical knowledge of metal panel roofing systems. The inspector surveys the roof, identifying distresses and determining severity levels, specific defects, and quantities. The recorder logs the data on the worksheet and assists in measuring distress

quantities when required. The recorder must also serve as the safety observer for the team.

Supplies

The following supplies are required to perform the inspection and can be carried in a satchel when on the rooftop:

- inspection and distress manual (this document)
- pencil and clipboard
- copies of the *Roof Inspection Worksheet* (photocopy from Appendix C)
- small hacksaw blade (for probing)
- · lumber crayon or wax pencil
- measuring tapes (12 ft and 100 ft recommended)
- large plastic bag (for collecting rooftop debris)
- binoculars
- slope meter.

General inspection guidelines

The following is a list of general guidelines for the roof inspection:

- Walk the outside of the building and look for water stains, efflorescence, missing mortar, spalling brick, and gutter and downspout problems. Note any findings in the Remarks Section on the reverse side of the *Roof Inspection Worksheet*.
- Ask facility manager or building occupants if there are any known water leakage problems.
- Walk the interior of the building and examine the ceiling for water marks or other evidence of problems. Note rusting or other signs of water penetration in the Remarks Section. Occupants can often provide valuable information.
- If accessible, inspect attic space to verify type of deck and identify problems.
- When on the rooftop, be careful not to damage the roof. Do not step on unsupported flashings or seams.
- If snow, frost, or visible moisture is present on the roof, postpone the inspection until the roof is clear and dry.
- Wherever possible, measure lengths and areas to determine distress quantities. Using estimates in place of measurements compromises the rating accuracy. Pacing to find lengths, measuring number of panels

and counting the quantity of fasteners per panel, or other numerical estimating techniques are preferable to "eyeball" estimates.

- If more than one distress severity level is found in a localized area, count the entire area at the highest severity level present.
- Note in the Remarks Section any other problems that are not included in the lists of flashing and panel distresses.
- Once a panel has been determined to have a defect that by its definition requires panel replacement (e.g., Localized Surface Deterioration high severity defect #2, SD-H-2), do not count other distresses on that same panel.

Survey preparation

It may be necessary for the survey team to contact the building superintendent or custodian for assistance in gaining access to the roof. When accessing the roof, the inspectors should assess safety conditions and determine if they can walk on the roof surface safely. If the roof cannot be walked safely (e.g., slopes rising more than 5 inches in 12 inches), alternative inspection methods should be used, such as use of a lift or chicken ladders. The inspectors should always be aware of and abide by all safety requirements of governing authorities.

Roof section plan validation

Before beginning the inspection, the existing roof section plan on the *Roof Inspection Worksheet* should be checked for completeness and accuracy. Any missing, extraneous, or inaccurate depictions of physical roof features should be revised before proceeding with the survey (see Chapter 2). All section area and roof feature dimensions should be checked for accuracy as deemed necessary. If a roof section plan has not been drawn on the worksheet at the time of the inspection, it should be developed following the guidelines described Chapter 2.

Determining total length of flashed perimeter and curb flashings

The calculations used in the roof condition rating procedures require a total quantity of flashed perimeter length and curb flashing lengths for the section being evaluated. For a typical roof section, the flashed perimeter length is the total perimeter length of the roof section. Curb flashings are the flashed terminations around platforms that support raised rooftop equipment and features such as access hatches. The team should measure

and establish these two quantities before starting the distress survey. Both quantities should be entered in the appropriate fields in the header section of the *Roof Inspection Worksheet* (see Figure 19). If values were entered on the sheet before the inspection, the team should verify for accuracy.

Determining total number of through-panel fasteners

For this inspection procedure, through-panel fasteners are defined as fasteners that penetrate any part of a metal panel. These fasteners can be screws that may have gaskets and/or washers, or various types of rivets and nails. Fasteners that do not penetrate any part of a system panel (such as those that have their head or washer in contact with the flashing metal) are considered flashing fasteners, and are not included in this count.

The inspection team should count and record the total number of exposed through panel fasteners on the roof section. The precision of this count is not critical for the assessment process; a 10% error is acceptable. Counting number of fasteners per panel or per area and extrapolating for the entire roof section will suffice. The total quantity of through-panel fasteners should be entered in the appropriate field in the header section of the *Roof Inspection Worksheet* (see Figure 18). If a value was entered on the sheet before the inspection, the team should verify it for accuracy.

Distress survey

Inspectors must be able to identify the various distresses and defects accurately and follow the inspection procedure closely to obtain meaningful, consistent, and repeatable results. When performing the inspection, identify each distress as it is encountered. Using the criteria defined in Chapters 4 and 5, determine its severity level and the specific defect that best defines the problem. Measure the quantity of the defect. A description of the valley flashing distresses and specific defects is shown in Figure 18.

For each encountered distress, enter the two-letter distress abbreviation, the letter representing the severity level (L - low, M - medium, H - high), the specific defect number, and the quantity information in the columns on the right side of the *Roof Inspection Worksheet*. Each individual distress entry is assigned an identification number, starting with 1 (ID # in column 1) and numbering consecutively. Record the location of each distress on the roof plan using the identification number, as shown in Figure 16. If, during the inspection, the worksheet becomes filled, continue re-

cording on a second worksheet. Appendix B contains an abbreviated list of identifiers for all the distress/severity level/defect combinations. The list is designed to help inspectors rapidly identify and record defects. A copy of the list can be attached to the bottom of a long [8 x 14 in.] clipboard so it is visible below *Roof Inspection Worksheet*.

Perform the distress survey of each roof section using the following steps:

- 1. Inspect the perimeter. Establish a starting point at one corner of the roof section. Walk the perimeter, examining all eave, rake, and other termination flashings. Fill in the worksheet as the inspection proceeds.
- 2. After inspecting the perimeter, walk the roof area, using an established pattern, inspecting all other flashings. This includes ridges, hips, valleys, transitions, flanged metal, curb, and penetration flashings. Establish a starting point at one corner of the roof section. Covering 10- to 15-ft wide strips, walk back and forth across the roof section surveying the entire area.
- 3. When specific defects occur uniformly on a large area, the following representative sampling technique can be used. Select a portion of the roof (e.g., number of panels, 1000 sq ft of panels, or 20 lineal ft of flashing) and measure the distress in the sample area. Then, by extrapolation, estimate the quantity of that distress for the total portion of the panels or flashing affected. Record the distress information as a single entry with one identification number on the *Roof Inspection Worksheet*. The boundaries of the overall area or length, which is represented by the sampling, should be shown on the roof section plan.

Determining the FCI and PCI

The FCI and PCI of a roof section are determined from the information recorded on the *Roof Inspection Worksheet*. The condition indexes can be calculated by entering the distress information into the web-based ROOFER application. The indexes can also be determined manually using the methodology described in Appendix B.

4 Flashing Distresses

Flashing Fastener (FF)

Description

This distress pertains to all flashing securement fasteners that do not penetrate the roof panel. Fasteners can be screws that may have gaskets and/or washers, or various types of rivets and nails.

Note: Flashing fasteners that penetrate the roof panel are considered panel fastener distresses.

Note: Flashing fasteners that do not penetrate the roof panel but penetrate the valley flashing are considered valley flashing distresses.

Severity levels

Medium

1. Fastener has no flexible gasket (where one was originally installed) or has a flexible gasket that is deteriorating but appears to be watertight; or fastener is corroded, improperly seated, or has a sealant repair but appears to be watertight.

High

1. Fastener or flexible gasket (where one was originally installed) is loose, deteriorated or missing and is allowing water to penetrate the roofing system; or fastener has an enlarged hole that is allowing water to penetrate the roofing system.

Measurement

Count the total number of defective fasteners.

Density


Problem Density =
$$\frac{A}{B} \times 100$$

A = Number of defective fasteners.

B = Total length of roof section perimeter and metal curb flashings (ft).

Note: The problem density is calculated for each observed severity level.

FF reference photographs



FF-H-1: Fastener or flexible gasket (where one was originally installed) is loose, deteriorated or missing and is allowing water to penetrate the roofing system; or fastener has an enlarged hole that is allowing water to penetrate the roofing system.



FF-H-1: Fastener or flexible gasket (where one was originally installed) is loose, deteriorated or missing and is allowing water to penetrate the roofing system; or fastener has an enlarged hole that is allowing water to penetrate the roofing system.

Localized Flashing Surface Deterioration (FD)

Description

Degradation of finish on the flashing, such as colored paint, clear coat, anodized finish; degradation of the field-applied coating; or metal corrosion, and only as it differs from remainder of roof.

Note: If SD-M-2 is determined for the roof section, then this defect does not apply separately; it is captured in the defect for the panel.

Severity levels

Medium

1. Flashing has localized loss of applied finish, or localized metal corrosion.

Measurement

Measure the lineal feet of defective flashing.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of defective flashing (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

FD reference photograph




FD-M-1: Flashing has localized loss of applied finish or localized metal corrosion.

Panel Closure (PC)

Description

Pre-formed nonmetallic insert or metal panel closure (Z-clip or boxed end closure) that seals the openings in the panel profile. Panel closures are found on ridges, hips, eaves, walls—wherever panels terminate.



Panel closure details (source: NRCA).

Severity levels

Medium

1. Panel closure is misaligned but appears to be watertight.

2. Pre-manufactured seam cap does not fit properly.

High

1. Non-metal panel closure is deformed, misaligned, damaged, or missing; allowing water to penetrate the roofing system.

2. Metal panel closure is deformed, misaligned, or missing; allowing water to penetrate the system.

Measurement

Measure the lineal feet of defective panel closures. Count individual defective panel closures as a minimum of 1 foot.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of defective closures (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

PC reference photographs



PC-M-1: Panel closure is misaligned but appears to be watertight.



PC-M-2: Pre-manufactured seam cap does not fit proper ly.



PC-H-1: Non-metal panel closure is deformed, misaligned, damaged or missing; allowing water to penetrate the roofing system.



PC-H-1: Non-metal panel closure is deformed, misaligned, damaged or missing; allowing water to penetrate the roofing system.




PC-H-2: Metal panel closure is deformed, misaligned, or missing; allowing water to penetrate the system.

Eave Flashing (EA)

Description

Eave flashing is the metal flashing at the draining edge of a roof.



Eave flashing details (source: NRCA).

Severity levels

Medium

1. Eave flashing is displaced but appears to be watertight.

High

- 1. Eave flashing has holes.
- 2. Non-cleated eave flashing is displaced and allowing water to penetrate the system.
- 3. Cleated eave flashing is displaced or disengaged.
- 4. Eave flashing has open joints or butt joints.
- 5. Eave flashing is missing.

Measurement

For H-1, H-2, H-3, H-4, and H-5 defects, measure the lineal feet of defective flashing. Individual defects shall be counted as a minimum of 1 foot. If the distance between defects is less than 1 foot, include the length between defects.

For M-1 defect, count the entire length of each defective flashing piece (typically 10 feet).


Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of eave flashing defects (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

EA reference photograph




EA-H-3: Cleated eave flashing is displaced or disengaged.

Rake Edge Flashing (RE)

Description

Rake edge metal flashing is installed along the inclined edge of a sloped roof. It can be similar to eave flashing, providing protection for underlying building surfaces, and allows water to drip away from vertical surfaces. In addition, some panel profiles have a raised rake cap.



Rake edge flashing details (source: NRCA).

Severity levels

Medium

1. Rake flashing is loose or displaced but appears to be watertight and does not compromise panel securement.

High

- 1. Rake flashing has holes.
- 2. Rake flashing is loose, displaced, or missing; allowing water to penetrate the roofing system and/or compromising panel securement.
- 3. Rake flashing is installed so that water is running against lap.
- 4. Rake flashing has open joints or butt joints.

Measurement

For H-1 and H-4 defect, measure the lineal feet of defective flashing. Individual defects shall be counted as a minimum of 1 foot. If the distance between defects is less than 1 foot, include the length between defects.

For M-1, H-2, and H-3 defects; count the entire length of each defective flashing piece (typically 10 feet).

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of rake edge flashing defects (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

RE reference photographs



RE-H-1: Rake flashing has holes.



RE-H-2: Rake flashing is loose, displaced or missing, allowing water to penetrate the roofing system and/or compromising panel securement.



RE-H-2: Rake flashing is loose, displaced, or missing, allowing water to penetrate the roofing system and/or compromising panel securement.




RE-H-4: Rake flashing has open joint or butt joints.


Ridge Cap, Hip Cap (CP)

Description

Ridge caps and hip caps provide roofing protection at the terminations of adjoining, sloping roof planes. The ridge cap protects the uppermost, horizontal external angle; the hip cap covers the inclined external angle formed by the intersection of two sloping roof planes. Venting and nonventing applications determine the fastening and sealing requirements.



Ridge cap and hip cap flashing details (source: NRCA) (cont'd).



Ridge cap and hip cap flashing details (source: NRCA) (concluded).

Severity levels

Medium

Ridge or hip cap flashing is disengaged but appears to be watertight.

High

- 1. Ridge or hip cap flashing has holes that require localized repair.
- Ridge or hip cap flashing is deformed or disengaged and allowing water to penetrate the roofing system; or evidence of ponding at a lap or seam.
- 3. Ridge or hip cap flashing is missing.
- 4. Hip cap flashing has joints that are bucking water.
- 5. Ridge or hip cap flashing has open joints or butt joints.

Measurement

For H-1 and H-5 defects, measure the lineal feet of defective flashing. Individual defects shall be counted as a minimum of 1 foot. If the distance between defects is less than 1 foot, include the length between defects.

For M-1, H-2, H-3, and H-4 defects; count the entire length of each defective flashing piece (typically 10 feet).

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of ridge or hip cap flashing defects (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

Note: The problem density is calculated for each observed severity level.

CP reference photographs



CP-M-1: Ridge or hip cap flashing is disengaged but appears to be watertight.



CP-H-2: Ridge or hip cap flashing is deformed or disengaged and allowing water to penetrate the roofing system; or evidence of ponding at a lap.



CP-H-3: Ridge or hip cap flashing is missing.




CP-H-5: Ridge or hip cap flashing has open joint or butt joints.

Valley Flashing (VF)

Description

Valley flashing is flashing where the intersection of two sloping roof planes forms a "V". Fasteners that penetrate the valley flashing but do not penetrate the roof panel shall be considered as valley flashing defects and not flashing fastener defects. Patches in the valley flashings shall be considered as valley flashing defects and not flashing patch defects.

Note: If fasteners penetrate the roof panel, the distress is considered a panel fastener distress.



Valley flashing details (source: NRCA).

Severity levels

Low

- 1. Valley flashing fastener is located in the valley but appears to be water-tight.
- 2. Valley flashing patch appears to be watertight

Medium

1. Valley flashing fastener has no flexible gasket or has a flexible gasket that is deteriorating but appears to be watertight; or fastener is corroded, improperly seated, or has a temporary repair but appears to be watertight.

High

 Valley flashing fastener or flexible gasket is loose, deteriorated, or missing and is allowing water to penetrate the roofing system; or fastener has an enlarged hole that is allowing water to penetrate the roofing system.

- 2. Valley flashing has holes.
- 3. Valley flashing has open joints or butt joint, or joints that are bucking water.
- 4. Panel end that terminates in valley has become disengaged.
- 5. Valley flashing patch is allowing water to penetrate the roofing system or is inappropriate.
- 6. Valley flashing is missing.

Measurement

For L-2, H-2, H-3, H-4, H-5, and H-6 defects, measure the lineal feet of defective flashing. Individual defects shall be counted as a minimum of 1 foot. If the distance between defects is less than 1 foot, include the length between defects.

For L-1, M-1, and H-1 defects; count the total number of defective fasteners.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of valley flashing defects (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

VF reference photographs



VF-L-1: Valley flashing fastener is located in the valley but appears to be watertight.



VF-L-1: Valley flashing fastener is located in the valley but appears to be watertight.



VF-H-3: Valley flashing has open joints or butt joint, or joints that are bucking water.




VF-H-3: Valley flashing has open joints or butt joint, or joints that are bucking water.

Headwall Transition Flashing (HT)

Description

Flashing for a roof section that transitions to a headwall. This flashing requires roof-to-wall flashing, positively attached to the roofing system. A similar flashing detail is used to transition from a metal roof plane to another metal roof plane on the upslope side that is at a steeper slope.



Headwall transition flashing details (source: NRCA).

Severity levels

Medium

1. Transition flashing is disengaged or loose but appears to be watertight.

High

- 1. Transition flashing has holes.
- 2. Transition flashing is disengaged or loose and is allowing water to penetrate the roofing system.
- 3. Transition flashing is missing or deformed and is allowing water to penetrate the roofing system.
- 4. Transition flashing has open joints or butt joints, or joints that are bucking water.

Measurement

For H-1 and H-4 defects, measure the lineal feet of defective flashing. Individual defects shall be counted as a minimum of 1 foot. If the distance between defects is less than 1 foot, include the length between defects.

For M-1, H-2, and H-3 defects, count the entire length of each defective flashing piece (typically 10 feet).

Density

Problem Density =
$$\frac{A}{B} \times 100$$


A = Length of roof to headwall transition flashing defects (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

Sidewall Transition Flashing (ST)

Description

A roof panel that transitions to a sidewall and requires a roof-to-wall flashing.



Sidewall transition flashing details (source: NRCA).

Severity levels

Medium

1. Transition flashing is disengaged or loose but appears to be watertight.

High

1. Transition flashing has holes.

- 2. Transition flashing is disengaged or loose and is allowing water to penetrate the roofing system.
- 3. Transition flashing has open joints or butt joints, or joints that are bucking water.
- 4. Transition flashing is missing or deformed and is allowing water to penetrate the roofing system.

Measurement

For H-1, and H-3 defects, measure the lineal feet of defective flashing. Individual defects shall be counted as a minimum of 1 foot. If the distance between defects is less than 1 foot, include the length between defects.

For M-1, H-2 and H-4 defects; count the entire length of each defective flashing piece (typically 10 feet).

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of roof to sidewall transition flashing defects (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

ST reference photographs



ST-H-2: Transition flashing is disengaged or loose and is allowing water to penetrate the roofing system.




ST-H-3: Transition flashing has open joints or butt joints, or joints that are bucking water.

Continuous Roof-to-Wall Panel Transition Flashing (RW)

Description

All panel profiles that transition from one roof slope to a greater roof slope where the panels are continuous.



Continuous roof-to-wall panel transition flashing details (source: NRCA).

Severity levels

Low

1. Continuous roof-to-wall panel transition flashings are rated low severity as a minimum due to the maintenance problems associated with them.

High

1. Transition flashing has loose, deformed, or missing seam cover.

Measurement

For L-1 defect, measure the lineal feet of defective flashing. Individual defects shall be counted as a minimum of 1 foot. If the distance between defects is less than 1 foot, include the length between defects.

For H-1 defect, count each defective seam covers as one each.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of continuous roof-to-wall panel transition flashing defects (ft). B = Total length of roof section perimeter and metal curb flashings (ft).

Built-in Gutters (IG)

Description

Built-in gutter is a gutter that is flashed at its entire perimeter.

Severity levels

Low

1. Interior gutter is lined with elastomeric membrane or coating and appears to be watertight.

Medium

1. Interior gutter is not lined with elastomeric membrane or coating and appears to be watertight.

High

- 1. Interior gutter is not lined with elastomeric membrane or coating and has holes, splits or open joints.
- 2. Interior gutter having elastomeric membrane or coating has holes splits or open joints.
- 3. Interior gutter or drain is clogged.

Measurement

Measure the lineal feet of defective flashing. Individual defects shall be counted as a minimum of 1 foot. If the distance between defects is less than 1 foot, include the length between defects.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of interior gutter defects (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

IG reference photographs



IG-L-1: Interior gutter is lined with elastomeric membrane or coating and appears to be watertight.



IG-M-1: Interior gutter is not lined with elastomeric membrane or coating and appears to be watertight.



IG-H-1: Interior gutter is not lined with elastomeric membrane or coating and has holes, splits or open joints.




IG-H-3: Interior gutter or drain is clogged.

Flexible Boot Flashings (FB)

Description

A flexible boot flashing is a flashing that extends from the panel surface up the penetration where it seals around the penetration. Typically these flashings are mechanically fastened to the panel surface. The top is typically a friction fit seal which is then made into a compression seal using a draw band.

Note: Penetration that blocks drainage should be addressed in the flanged metal and raised curb flashing distress (FM H-1).



Flexible boot flashing details (source: NRCA).

Severity levels

Low

1. Flexible boot flashings are rated low-severity as a minimum due to the maintenance problems associated with them.

Medium

1. Flexible boot flashing has loose, missing, corroded or misaligned drawband.

High

1. Flexible boot is missing or has holes; or flexible boot flashing interferes with a panel seam and is allowing water to penetrate the system.

- 2. Flexible boot flashing has deformed securement ring, allowing water to penetrate the roofing system.
- 3. Flexible boot flashing has failed or missing sealant around the drawband, allowing water to penetrate the roofing system.

Measurement

Count each flexible boot flashing as 1 ft at the highest observed severity level.


Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of flexible boot flashing defects (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

FB reference photographs



FB-L-1: Flexible boot flashings are rated low-severity as a minimum due to inherent maintenance problems.




FB-M-1: Flexible boot flashing has loose, missing, corroded or misaligned draw band.



FB-H-1: Flexible boot is missing or has holes; or flexible boot flashing interferes with a panel seam and is allowing water to penetrate the system.



FB-H-1: Flexible boot is missing or has holes; or flexible boot flashing interferes with a panel seam and is allowing water to penetrate the system.




FB-H-2: Flexible boot flashing has deformed securement ring, allowing water to penetrate the roofing system.

Flanged Metal and Raised Curb Flashing (FM)

Description

A flanged metal or raised flashing extends from the panel surface up the sides of a square, curbed or round penetration. The surface that rests on or under the panel is made of metal with a welded, soldered, or otherwise watertight seal at transitions. These flashings can be mechanically attached to the panel and may require sealant or a membrane of elastomeric seal at the outside of the panel flange. The top may or may not be tight against the penetration. The top may turn down into a pipe penetration, have a separate cap that covers the top, or may rely on an "umbrella" or storm collar to keep water from entering at the top of the flashing. The top may also be counterflashed by a separate cap or a skylight frame or part of the equipment that is mounted to the top of the curb.



Flanged metal and raised curb flashing details (source: NRCA).

Severity levels

Low

1. Flanged metal and raised curb flashings are rated low-severity as a minimum due to the maintenance problems associated with them.

Medium

- 1. Flashing flange on upslope side is mounted on top of panel, bucking water, but appears to be watertight
- 2. Flashing flange on downslope side is mounted below panel, bucking water, but appears to be watertight.
- 3. Sealant around umbrella is deteriorating, torn, or deformed, but appears to be watertight.

High

- 1. Flashing impedes drainage.
- 2. Flashing has holes.
- 3. Flashing joint has failed and is allowing water to penetrate the roofing system.
- 4. Flashing flange on upslope side is mounted on top of panel, bucking water, and is allowing water to penetrate the roofing system.
- 5. Flashing flange on downslope side is mounted below panel, bucking water, and is allowing water to penetrate the roofing system.
- Flashing has missing seam closure on downslope side.
- 7. Flashing flange is open or unsealed.
- 8. Top of pipe flashing is open.
- 9. Sealant around umbrella is missing or is allowing water to penetrate the roofing system.

Measurement

Measure the lineal feet of defective flashing. Individual defects shall be counted as a minimum of 1 foot. If the distance between defects is less than 1 foot, include the length between defects.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of flanged metal or raised curb flashing defects (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

Note: The problem density is calculated for each observed severity level.

FM reference photographs



FM-M-1: Flashing flange on upslope side is mounted on top of panel, bucking water, but appears to be watertight.



FM-H-1: Flashing impedes drainage.



FM-H-2: Flashing has holes.



FM-H-5: Flashing flange on downslope side is mounted below panel, bucking water, and is allowing water to penetrate the roofing system.



FM-H-7: Flashing flange is open or unsealed.




FM-H-9: Sealant around umbrella is missing or is allowing water to penetrate the roofing system.

Ancillary Flashing (AF)

Description

Ancillary flashing includes counterflashing; any sheet metal coping cap or elastomeric bellows expansion joint cover that serves as part of the counterflashing; or cover over a detail such as an equipment curb or termination flashing. Ancillary flashing protects the top termination of the vertical flashing and sheds water away from it. Properly lapped exterior siding or cladding can perform the function of ancillary metal flashing.

Note: Fasteners that do not penetrate the roof panel that is part of the flashing component are treated as a flashing fastener distress. If they do penetrate the roof panel, they are considered a panel fastener distress.



Ancillary flashing details (source: NRCA).

Severity levels

Low

1. Curb/coping cap flashing is deformed with evidence of water ponding at a location that is not adjacent to a lap or seam; or counterflashing is deformed but still functioning.

2. Elastomeric bellows expansion joint cover is used.

Medium

- 1. Ancillary flashing has holes on a vertical surface.
- 2. Curb/coping cap has unflashed or improperly flashed penetration passing through, but appears to be watertight.

High

- 1. Ancillary flashing has holes through it or severe deterioration on a horizontal surface.
- 2. Ancillary flashing is missing or deformed; or there is evidence of water ponding at a lap or seam.
- 3. Ancillary flashing is displaced.
- 4. Ancillary flashing has a failed soldered joint, an open joint, a butt joint, or joint covers missing from where originally installed.
- 5. Ancillary flashing has joints that are bucking water.
- 6. Sealant at reglet, top of counterflashing, or sealed joint is missing or no longer functioning.
- Counterflashing, exterior siding, or cladding does not extend over top of transition flashing where originally installed or required.
- 8. Curb/coping cap has unflashed or improperly flashed penetration passing through it that is allowing water to penetrate the roofing system.
- 9. Top of transition flashing is not properly counterflashed or terminated.

Measurement

For L-1, M-1, H-4, H-6, and H-9 defects, measure the lineal feet of defective flashing. Individual defects shall be counted as a minimum of 1 foot. If the distance between defects is less than 1 foot, include the length between defects.

For L-2, M-2, H-3, H-5, H-7, and H-8 defects, count the entire length of each defective flashing piece (typically 10 feet).

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of ancillary flashing defects (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

Note: The problem density is calculated for each observed severity level.

AF reference photographs



AF-H-6: Sealant at reglet, top of counterflashing, or sealed joint is missing or no longer functioning.



AF-H-9: Top of transition flashing is not properly counterflashed or terminated.

Flashing Patch (FR)

Description

Post-construction application of material applied to the flashing metal that is intended as a repair. Topical application of sealant is an example of a flashing patch. Random application of sealant that is not performing a waterproofing function is not considered as patching. Patches in the valley flashings shall be considered as valley flashing defects and not flashing patch defects.

Note: A flashing fastener that has a sealant repair is counted as a flashing fastener distress.

Severity levels

Low

1. Flashing patch appears to be watertight and does not require a more permanent repair.

Medium

1. Flashing patch that appears to be watertight, but requires a more permanent repair.

High

1. Flashing patch is allowing water to penetrate the roofing system.

Measurement

Measure the lineal feet of flashing component that is patched.

When large quantities of this problem are present, especially on large roofs, the representative sampling technique can be used.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of patched flashing component (ft).

B = Total length of roof section perimeter and metal curb flashings (ft).

Note: The problem density is calculated for each observed severity level.

FR reference photographs



FR-L-1: Flashing patch appears to be performing a waterproofing function and appears to be watertight and does not require a more permanent repair.



FR-M-1: Flashing patch, which appears to be performing a waterproofing function, appears to be watertight but requires a more permanent repair.



FR-M-1: Flashing patch, which appears to be performing a waterproofing function, appears to be watertight but requires a more permanent repair.



FR-M-1: Flashing patch, which appears to be performing a waterproofing function, appears to be watertight but requires a more permanent repair.



 $\ensuremath{\mathsf{FR}\text{-H-1}}\xspace$ FR-H-1: Flashing patch is allowing water to penetrate the roofing system.



 $\label{eq:FR-H-1:Flashing} \mbox{ FR-H-1: Flashing patch is allowing water to penetrate the roofing system.}$

5 Metal Panel Distresses

Section-Wide Surface Deterioration (SW)

Description

Degradation of factory-applied finish on the panel, such as colored paint, clear coat, anodized finish; degradation of the field-applied coating; or metal corrosion. This defect should be used to characterize an entire roof section. For localized areas of surface deterioration, use the Localized Surface Deterioration distress.

Severity levels

Low

1. Applied finish exhibits chalking, fading, or scratching over the entire roof section, but underlying corrosion is not apparent.

Medium

1. Base metal or applied finish exhibits chalking, fading, or scratching over the entire roof section, requiring a coating or surface treatment repair.

High

1. Base metal exhibits corrosion over the entire roof section, requiring a roof replacement.

Measurement

By definition, count the square feet of the entire area of the roof section.

Density

By definition, count the entire area of the roof section.


SW reference photographs



SW-L-1: Applied finish exhibits chalking, fading, or scratching over the entire roof section, but underlying corrosion is not apparent.



SW-M-1: Base metal or applied finish exhibits chalking, fading, or scratching over the entire roof section, requiring a coating or surface treatment repair.



SW-M-1: Base metal or applied finish exhibits chalking, fading, or scratching over the entire roof section, requiring a coating or surface treatment repair.



SW-H-1: Base metal exhibits corrosion over the entire roof section requiring a roof replacement.

Localized Surface Deterioration (SD)

Description

Degradation of factory-applied finish on the panel, such as colored paint, clear coat, anodized finish; degradation of the field-applied coating; or metal corrosion

Severity levels

Medium

- 1. Localized loss of applied finish or localized metal corrosion.
- 2. Metal panel finish exhibits degradation caused by grease, solvent, or oil drippings.

High

- 1. For panel system that has mechanically interlocked seams, panel has corrosion holes that require localized repair.
- 2. Metal panel finish exhibits degradation caused by grease, solvent or oil drippings that require panel replacement.

Note: Once any panel has a distress that requires panel replacement, do not count other distresses on that same panel.

Note: Due to mechanical seaming, mechanically interlocked panels are typically difficult to replace, and localized repairs would likely be made in lieu of panel replacement.

Measurement

For M-1, M-2, and H-1 defects, measure the square feet of defective panel area.

For H-2 defect, measure the square feet of each entire defective panel. (Repair requires replacement of the entire panel.)

When large quantities of this problem are present, especially on large roofs, the representative sampling technique can be used.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Area of surface deterioration or area of defective panels (sq ft).

B = Total area of roof section being rated (sq ft).

Note: The problem density is calculated for each observed severity level.

SD reference photographs



SD-M-1: Localized loss of applied finish or localized metal corrosion.



SD-M-1: Localized loss of applied finish or localized metal corrosion.



SD-H-1: For panel system that has mechanically interlocked seams, panel has corrosion holes that require localized repair .

Panel Fastener Defect (PF)

Description

This defect pertains to fasteners that penetrate any part of the panel. Fasteners can be screws that may have gaskets and/or washers, or various types of rivets and nails. All fasteners with the fastener head or washer against flashing metal and the fastener not penetrating the panel are accounted for as flashing fastener distress.

Severity levels

Medium

1. Fastener has no flexible gasket (where one was originally installed) or has a flexible gasket that is deteriorating but appears to be watertight; or fastener is corroded, improperly seated, or has a sealant repair but appears to be watertight.

High

 Fastener, flexible gasket (where one was originally installed) and/or metal washer is loose, deteriorated, or missing; allowing water to penetrate the roofing system; or fastener has an enlarged hole that is allowing water to penetrate the roofing system.

Measurement

Count the total number of defective fasteners.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Number of defective fasteners (count) for separate cap, integral cap, and mechanically interlocked seam systems.

B = Total area of roof section being rated (sq ft).

For lap seam systems


B = Total number of panel fasteners (count).

Note: The problem density is calculated for each observed severity level.

PF reference photographs



PF-M-1: Fastener has no flexible gasket (where one was originally installed) or has a flexible gasket that is deteriorating but appears to be watertight; or fastener is corroded, improperly seated, or has a sealant repair but appears to be watertight.



PF-H-1: Fastener, flexible gasket (where one was originally installed) and/or metal washer is loose, deteriorated or missing; allowing water to penetrate the roofing system; or fastener has an enlarged hole that is allowing water to penetrate the roofing system.

Damaged Panel (DP)

Description

Dented deformed or kinked panel; or holes, splits, or tears in the panel.

Note: Oil canning of the panel is not considered a defect because it is primarily an aesthetic issue and does not require repair.

Severity levels

Low

1. Panel is dented, deformed, or kinked with no deformation of the seam, no loss of coating, and no corrosion; appears to be watertight.

Medium

1. Panel is dented, deformed or kinked, allowing ponding water and/or corrosion.

High

- 1. For panel system that has mechanically interlocked seams, panel has holes, splits, or tears that require localized repairs.
- 2. For panel system that does not have mechanically interlocked seams, panel has holes, splits, or tears that require panel replacement.

Note: Once any panel has a distress that requires panel replacement, do not count other distresses on that same panel.

Note: Due to mechanical seaming, mechanically interlocked panels are typically difficult to replace, and localized repairs would likely be made in lieu of panel replacement.

Measurement

For L-1, M-1, and H-1 defects, measure the square feet of affected panel area. If the distance between holes, splits, or tears are less than 1 ft, count them as one defect.

For H-2 defect, measure surface area of each entire distressed panel. (Repair requires replacement of entire panel.)

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Area of damaged panel or area of defective panels (sq ft).

B = Total area of roof section being rated (sq ft).

Note: The problem density is calculated for each observed severity level.

DP reference photographs




DP-L-1: Panel is dented, deformed, or kinked with no deformation of the seam, no loss of coating, and no corrosion; and appears to be watertight.



DP-M-1: Panel is dented, deformed or kinked, allowing ponding water and/or corrosion.



DP-H-1: For panel system that has mechanically interlocked seams, panel has holes, splits, or tears that require localized repairs.



DP-H-2: For panel system that does not have mechanically interlocked seams; panel has holes, splits, or tears that require panel replacement.

Displaced Panel (DL)

Description

Displaced or missing panels.

Severity levels

High

1. Panel is loose or displaced and requires repositioning and resecurement.

2. Panel is missing and requires replacement.

Note: Once any panel has a distress that requires panel replacement, do not count other distresses on that same panel.

Measurement

Measure the square feet of the area of each entire distressed panel.

Density


Problem Density =
$$\frac{A}{B} \times 100$$

A = Area of displaced panels (sq ft).

B = Total area of roof section being rated (sq ft).

Note: The problem density is calculated for each observed severity level.

DL reference photograph



DL-H-2: Panel is missing and requires replacement.

Panel Patch (PA)

Description

Post-construction application of material applied to the metal panel that is intended as a repair. Topical application of sealant that is not performing a waterproofing function is not considered a panel patch. Random application of sealant is not considered as patching.

Note: A replacement panel with the same profile, same materials, and same construction as the existing metal panel system is not considered a panel patch.

Note: A fastener that penetrates a panel that has sealant repair is counted as a panel fastener distress.

Severity levels

Low

1. Panel patch appears to be watertight, and does not require a more permanent repair.

Medium

1. Panel patch appears to be watertight and requires a more permanent repair.

High

1. Panel patch is allowing water to penetrate the roofing system.

Measurement

Measure the square feet of the panel patch.

When large quantities of this problem are present, especially on large roofs, a representative sampling technique can be used.

Density


Problem Density =
$$\frac{A}{R} \times 100$$

A = Area of patching (sq ft).

B = Total area of roof section being rated (sq ft).

Note: The problem density is calculated for each observed severity level.

PA reference photographs



PA-L-1: Panel patch appears to be performing a waterproofing function, appears to be watertight, and does not require a more permanent repair.



PA-H-1: Panel patch is allowing water to penetrate the roofing system.

Debris and Vegetation (DV)

Description

The accumulation of debris on the roof including foreign objects, vegetation that is growing on the roof, or grease, solvent or oil that is on the surface of the roof. Algae growth and related staining that does not affect the finish is not considered a defect because it does not affect performance, and is primarily an aesthetic problem.

Note: Grease, solvent, or oil drippings that have caused deterioration of the metal panel finish are considered to be panel surface deterioration defects.

Severity levels

Medium

- 1. A collection of foreign objects or vegetation not removed from the roof during the inspection; or grease, solvent, or oil drippings on the roof that cause no degradation of the panel's applied finish.
- 2. Evidence of tree branches making contact with the roofing system.

Measurement

Measure the square feet of the affected area. Each isolated case of debris and vegetation of less than 1 sq ft in area should be counted as 1 sq ft.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Area of debris and vegetation (sq ft).

B = Total area of roof section being rated (sq ft).

DV reference photographs



DV-M-1: A collection of foreign objects or vegetation not removed from the roof during the inspection; or grease, solvent, or oil drippings on the roof that cause no degradation of the panel's applied finish.



DV-M-1: A collection of foreign objects or vegetation not removed from the roof during the inspection; or grease, solvent, or oil drippings on the roof that cause no degradation of the panel's applied finish.



DV-M-2: Evidence of tree branches making contact with the roofing system.

Improper Equipment Supports (EQ)

Description

Improper equipment supports can includes pipe, conduit, and mechanical equipment supports (wood sleepers, channels, etc.) that are placed directly on the roof surface and/or anchored to the roof with penetrating fasteners.

Note: Equipment supports that are appropriately clamped to the seams and not to the flat of the panel are not considered improper equipment supports.

Severity levels

Low

1. All improper equipment supports are rated low severity as a minimum due to the maintenance problems associated with them.

Medium

- 1. The equipment support is bolted or fastened through the metal panel seam flashing and the bolt(s) appear to be sealed and watertight.
- 2. The equipment support has caused damage to surrounding panels but appears to be watertight.

High

- 1. The equipment support is bolted or fastened through the metal panel seams or flashing and allowing water to penetrate the roofing system.
- 2. The equipment support has caused damage to surrounding panels and is allowing water to penetrate the roofing system.

Measurement

Measure square feet of each improper equipment support. The minimum dimension for length and width of a support shall be 1 ft.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Area of improper equipment supports (sq ft).

B = Total area of roof section being rated (sq ft).

Note: The problem density is calculated for each observed severity level.

EQ reference photographs



EQ-L-1: All improper equipment supports are rated low severity as a minimum due to the maintenance problems associated with them.



EQ-L-1: All improper equipment supports are rated low severity as a minimum due to the maintenance problems associated with them.



EQ-H-1: The equipment support is bolted or fastened through the metal panel seams or flashing and allowing water to penetrate the roofing system.



EQ-H-1: The equipment support is bolted or fastened through the metal panel seams or flashing and allowing water to penetrate the roofing system.



EQ-H-2: The equipment support has caused damage to surrounding panels and is allowing water to penetrate the roofing system.

Mechanically Interlocked Seam Defect (MS)

Description

For mechanically interlocked seams, the seam is damaged or has become disengaged.

Severity levels

Low

1. Seam is deformed or flattened but appears to be watertight.

High

1. Seam is open or allowing water to penetrate the roofing system; or seam is disengaged.

Measurement

Measure the lineal feet of defective seam.

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of defective seams (lf).

B = Total area of roof section being rated (sq ft).


MS reference photographs




MS-L-1: Seam is deformed or flattened but appears to be watertight.



MS-L-1: Seam is deformed or flattened but appears to be watertight.



MS-H-1: Seam is open or allowing water to penetrate the roofing system; or seam is disengaged.



MS-H-1: Seam is open or allowing water to penetrate the roofing system; or seam is disengaged.

Integral Cap Seam Defect (IC)

Description

For integral cap seams, the seam is damaged or has become disengaged.

Severity levels

Low

1. Seam is deformed or flattened, but still engaged and appears to be watertight.

High

- 1. Seam is disengaged and requires localized repair.
- 2. Seam is disengaged due to panel deformation and requires panel replacement.

Note: Once any panel has a distress that requires panel replacement, do not count other distresses on that same panel.

Measurement

For L-1 and H-1 defects, measure the lineal feet of defective seams. If the distance between defects is less than 1 foot, include the length between defects

For H-2 defect, measure the square feet of the entire area of the affected panel. (Repair requires replacement of entire panel.)

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of defective seams (lf) or area of defective panels (sq ft).

B = Total area of roof section being rated (sq ft).

Separate Cap Seam Defect (SC)

Description

For separate cap seam, the seam is deformed, flattened, has not been sufficiently locked to cleat, or has become disengaged; or cap is missing.

Severity levels

Low

1. Seam is deformed or flattened, but still engaged and appears to be watertight.

High

- 1. Seam is disengaged, requiring localized repair.
- 2. Seam is damaged or missing, requiring cap replacement.
- 3. Panel is damaged at seam location, requiring panel and cap replacement.

Note: Once any panel has a distress that requires panel replacement, do not count other distresses on that same panel.

Measurement

For L-1, H-1 and H-2 defects, measure the lineal feet of defective seams. If the distance between defects is less than 1 foot, include the length between defects.

For H-3 defect, measure the square feet of the entire area of both adjacent panels. (Repair requires replacement of entire panel.)

Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of defective seams (lf) or area of defective panels (sq ft).

B = Total area of roof section being rated (sq ft).

Lap Seam Defect (LS)

Description

Lap seam is open or deformed.

Severity levels

High

1. Seam is open with no panel deformation, requiring localized repair.

2. Seam is open due to panel deformation, requiring panel replacement.

Note: Once any panel has a distress that requires panel replacement, do not count other distresses on that same panel.

Note: If seam is open due to misalignment of the panel, the defect should be counted as a displaced panel.

Measurement

For H-1 defect, measure the lineal feet of defective seams. If the distance between defects is less than 1 foot, include the length between defects.

For H-2 defect, measure the square feet of the entire area of the panels. (Repair requires replacement of entire panel.)


Density

Problem Density =
$$\frac{A}{B} \times 100$$

A = Length of defective seams or area of defective panels (sq ft).

B = Total area of roof section being rated (sq ft).

LS reference photographs



 $\ensuremath{\mathsf{LS}\text{-H-1}}\xspace$ Seam is open with no panel deformation, requiring localized repair.



LS-H-2: Seam is open due to panel deformation, requiring panel replacement.

Transverse Panel Lap Defect (PL)

Description

Defects in the panel end laps. Panel laps are transverse seams in the field of the panel or at the roof edge.

Severity levels

Medium

- 1. For cleated end lap, panel is disengaged from the cleat.
- 2. End lap joint between panels has failed sealant or open fishmouths.

High

1. Transverse panel lap is bucking water.

Measurement

Determine the lineal feet of defect by counting the total number of defective panel end laps and multiplying by the panel width.

Density

Problem Density =
$$\frac{A}{R} \times 100$$

A = Length of defective transverse panel end laps (lf).

B = total area of roof section being rated (sq ft).

PL reference photographs



PL-M-2: End lap joint between panels has failed sealant or open fishmouths.

Integrated Skylight Panel Defect (SP)

Description

Fiberglass skylights that are integrated into the roofing system. These panels typically have the same profile as the main roof panels and are installed in the same plane as the roof panels (not curbed). Integrated skylight panels are most often found in lap seam metal panel systems. Note that raised prefabricated skylights with curbs should be rated as flanged metal and raised curb flashings.

Note: These skylight panels can be very dangerous and should not be stepped on regardless of the age or condition of the panels. If no skylight cages are in place, enter a comment at visual inspection.

Severity levels

Low

1. Integrated skylight panels are rated low severity as a minimum due to their shorter service life as compared to the metal roofing system.

Medium

1. Skylight composite material exhibits visible fibers, significant discoloration, or other signs of degradation.

High

- 1. Joint between integrated skylight panel and adjacent metal panel is not watertight or is bucking water.
- 2. Integrated skylight panel has holes, splits, or tears, allowing water to penetrate the roofing system.

Measurement

Measure the square feet of the entire area of the integrated skylight panel.

Density

Problem Density
$$p = \frac{A}{B} \times 100$$

A = Area of defective integrated skylight panels (sq ft).

B = Total area of roof section being rated (sq ft).

Note: The problem density is calculated for each observed severity level.

SP reference photographs



SP-L-1: Integrated skylight panels are rated low severity as a minimum due to their shorter service life as compared to the metal roofing system.





SP-M-1: Skylight composite material exhibits visible fibers, significant discoloration or other signs of degradation.


References


- Bailey, D.M. August 2003. Micro ROOFER for Windows User Guide Version 2.0. ERDC/CERL SR-03-8. Champaign, IL: US Army Engineer Research and Development Center, Construction Engineering Research Laboratory (ERDC-CERL).
- Bailey, D.M. December 1999. *ROOFER: Steep Roofing Inventory Procedures and Inspection and Distress Manual for Asphalt Shingle Roofs*, USACERL TR-99/100/ADA378154. Champaign, IL: US Army Construction Engineering Research Laboratory (USACERL).
- Bailey, D.M. March 2010. *Membrane and Flashing Condition Indexes for Modified Bitumen Roofs*. ERDC/CERL Technical Report TR-10-5. Champaign, IL: ERDC-CERL.
- Bailey, D.M., D.E. Brotherson, W. Tobiasson, S. Foltz, and A. Knehans. April 1993. ROOFER: Membrane and Flashing Condition Indexes for Single-Ply Membrane Roofs - Inspection and Distress Manual. USACERL TR FM-93/11/ADA272573. Champaign, IL: USACERL.
- Bailey, D.M., D. Brotherson, W. Tobiasson, and A. Knehans. December 1989. *ROOFER:* An Engineered Management System (EMS) For Bituminous Built-Up Roofs. USACERL TR M-90/04/ADA218529. Champaign, IL: USACERL.
- Shahin, M.Y., D. Bailey, and D. Brotherson. September 1978a. *Membrane and Flashing Condition Indexes for Built-Up Roofs Volume I: Development of the Procedure*, USACERL TR M-87/13/ADA190367. Champaign, IL: USACERL.
- Shahin, M.Y., D. Bailey, and D. Brotherson. September 1978b. *Membrane and Flashing Condition Indexes for Built-Up Roofs Volume II: Inspection and Distress Manual*, Technical ReportM-87/13/ADA190368. Champaign, IL: USACERL.


Appendix A: Deduct Value Curves

















































Corrected Deduct Values for Flashing.






































Corrected Deduct Values for Panels.

Appendix B: Condition Index Calculation Methodology

The panel and flashing condition indexes and the overall roof condition index are computed by the web-based ROOFER application once the visual inspection data is entered into the database. To understand the condition index concept and methodology used in the calculations, the manual calculation process is described below.

Determine deduct values

Use information from the *Roof Inspection Worksheet* to complete the heading section of the *Roof Section Rating Form*. Transfer the quantities for each combination of distress type and severity level from the completed *Roof Inspection Worksheet* to the *Roof Section Rating Form* (see Figure B1 for the inspection data used for the presented example calculation). Flashing distresses are tabulated on the left side of the page and panel distresses on the right. Total the quantities for each severity of each distress, calculate each density using the equations in Chapters 4 and 5, and determine deduct values (DV) from the Deduct Value Curves in Appendix A. See Figure B2 for the completed *Roof Section Rating Form* using the example data.

Determine corrected deduct values

Tabulate flashing deduct values in descending order as shown below using the data obtained from Figure B1. Determine the sums of flashing deduct values (ΣDV) and the number of distresses with deduct values greater than 1 (q), then use these two values and the appropriate graph in Appendix A to determine corrected deduct values (CDV) for the flashing distresses. Circle the maximum value of CDV as shown.

DV	ΣDV	q	$\mathrm{CDV}_{\mathrm{flashing}}$
14	14	1	14
6	20	2	13
2	22	3	13

For this example the Maximum $CDV_{flashing} = 14$.

Repeat this process using the appropriate graph in Appendix A to determine the maximum corrected deduct value for the panels.

DV	Σ DV	q	$\mathrm{CDV}_{\mathrm{panels}}$
15	15	1	15
7	22	2	15
7	29	3	17
2	31	4	16

For this example the Maximum $CDV_{panel} = 17$

Compute flashing and panel condition indexes

Calculate flashing and panel condition indexes using the following equations:

$$PCI = 100 - Max. CDV_{panels}$$

For this data, FCI = 86 and PCI = 83. Using Figure B3, determine the corresponding descriptive condition ratings for both the flashing and panel components.

Compute roof condition index

Each individual index (FCI, PCI) reflects the component's ability to provide its intended service and indicates MRR needs. Since the components must interact to function as a roof system, they are dependent on each other. The indexes, in total, provide an assessment of the condition of an metal panel roof section. By combining these indexes, a roof condition index (RCI) can be calculated. This single index is useful for evaluating the overall condition of a roof section and for comparing conditions between roof sections. The RCI allows the user to rank individual roof sections in accordance with their ability to perform.

This relationship is defined by the following equation:

RCI =
$$(0.7 \text{ x lowest condition index}) + (0.3 \text{ x remaining condition index})$$
 [Eq 6]

The above equation give the greatest weight to the component with the lowest condition index and then modify it by adding "value" from the remaining index.

The following example illustrates how this relationship works:


Example:
$$FCI = 88$$
; $PCI = 91$

$$RCI = (0.7 \times 88) + (0.3 \times 91)$$


$$= 62 + 27$$

$$= 89$$

A completed *RCI Calculation Sheet* is shown in Figure B4.



ROOF SECTION RATING FORM										
BUILDING 625	SECTION	Α	DA	TE 15 DUNE ZO	2 0	CALC. BY				
FLASHED PERIMETER 524 FT CURB FLASHINGS 48 FT TOTAL 572 FT	THRU PANEL FAST	ENERS 53	6 AF	NEA 12,400 SO	FT C	CHKD. BY				
FD -Flash Surface Det ST -F PC -Panel Closure RW -F EA -Eave Flashing IG -F RE -Rake Edge Flashing FB -F CP -Ridge Hip Flashing FM -F VF -Valley Flashing AF -F FR -F	eadwall Tran idewall Tran bof to Wall Tran uilt-in Gutters lexible Boot	SD PF DP DL PA	-Locali: -Panel -Damage: -Displa: -Panel -Debris	Fastener IC -Ir d Panel SC -Se ced Panel LS -La	ch Inte tegral parate p Seam an Pane	Cap Seam Cap Seam 1 Lap				
DIS SEV QUANTITIES	TOT DEN D			QUANTITIES	-	DEN DV				
EA H 4+Z+10	16 2.8 6		_	112		1,9/ 7				
CP H ZO+10	30 5.2 1		_	35+20		5.44 15				
F/11 17 4	4 0,78 €	PF		10		1.1 7				
		DI	> L	44		0.36 7				
				7 4	441	7.36 /				
CORRECTED DEDUCT VALUE (CD FCI = 100 - CDV = 8 FLASHING RATING 5XC			DEDUCT VALUE (CDV) $- CDV = \frac{83}{VERY}$ ING		17					



RCI CALCULATION	SHEET	AGENCY/I	NST.:			
DATE: 6/15/2012	BLDG NO:	625	SECTION ID: /	7	AREA: 14400	SF
			ά			
ROOF SECTION	N WITH META	L PANEL RO	OFING			
		VALUE	LOWEST	OTH	ER	
ì	PCI	83	83			
	FCI	86		80	0	
			X 0.70	х о.		
			(A) 58.1	(B) Z	5.8	
			(A+B)	80	1	
			RCI	0		
						_
RATINGS						
	13	36 - 100	EXCELLENT			
		71 - 85	VERY GOOD			
		56 - 70	GOOD			
		41 - 55	FAIR			
		26 - 40	POOR			
		11 - 25	VERY POOR			
		0 - 10	FAILED			

B 4.

Appendix C: Blank Worksheets

The following pages contain facsimiles of all blank worksheets needed by an inspector performing a ROOFER steel panel roof evaluation. Photocopy them for use in the field.

Included at the end of the appendix is a field reference guide for flashing and panel distresses.

•			
BUILDING IDENTIFICA	TION SHEET	AGENCY / INST. NO.	:
DATE://	AGENCY / INST.:		
BUILDING NAME:			
BUILDING NUMBER:	DESIGN CATEGORY CO	ODE:	
TYPE CONST.:	FACILITY NUMBER:		
LOCATION:			
USE:		YEAR BUILT:	V
ROOF SECTIONS:			
BSF G CSF H D SF I E SF J	SF	K SF L SF M SF N SF O SF	R SF S SF
REMARKS:			
итатия	IG POOF PLAN		SCALE.

ROOF SECTION IDENT	IFICA	TION		AGENCY/INST.	:						
DATE:/	CTION ID:		AREA:	SF							
OCCUPANCY:		YEAR ORIG	÷.	CONST.:	Y	EAR LAST	REPLACED:				
10 GENERAL											
11 TYPE:											
12 ACCESS:											
20 STRUCTURAL FRAME							6				
21 TYPE:											
30 ROOF DECK											
31 STRUCTURAL DECK:				2							
32 ATTACHMENT SURFAC	E:	33 SLOPE:			3	4 DRAINAG	E:				
				IN 12							
40 UNDERLAYMENT											
41 TYPE:											
50 ROOF COVERING											
51 TYPE:							-				
52 BASE METAL:											
53 PANEL FINISH:											
54 PANEL ATTACHMENT:											
60 FLASHINGS											
61 TYPES:		62 ACCESS	SOR	IES:	6:		: Y/N/UNKNOWN # OF LAYERS				
70 REMARKS:	9.										

ROOF SECTION IDENTIFICATI	ON WORE	KSHEET	AGENCY/IN	NST.:						
DATE:/ BLDG. NO	.:	SECTIO	N ID:	AREA:	SF					
OCCUPANCY:	YEAR OF	RIG. CON	IST.:	YEAR LAST REP	LACED:					
10 GENERAL										
11 TYPE (check all): GABLE GAMBREL BARREL										
HIP MANSARD	SH	ED ME		RADIUS PA	ANEL					
12 ACCESS (check one): INTERNAL LADDER Permanent Temporary	Pe	NAL LAD rmanent mporary		PENTHOUSE ACCESSED F SECTION OTHER	ROM ADJ. (Sec.ID)					
20 STRUCTURAL FRAME										
21 TYPE (check one): STEEL Beams, Girders, Cols Long Sp Deck, Beams Trusses Bar Joists with Beams & Cols. Bar Joists with Bearing Walls Bar Joists with Combination	W00	_	ed Beams	SPECIAL Dome Space OTHER UNKNOW						
30 ROOF DECK	>									
NONCOMBUSTIBLE COMBUSTIBLE STEELWOOD BOARDSOTHER CONCRETE, STDPrecastPLYWOODUNKNOWNCast-in-PlaceWOOD FIBERNONE GYPSUM, PRECASTCONCRETE, LWTPRECAST CEMENT FIBERBulb-TeesClipped										

		E 0.35 (1.50
32	ATTACHMENT SURFACE (if appl:	icable):
	WOOD DECK	WOOD BATTENS OTHER
	OSB Panels	WOOD FRAMING
	Plywood Panels	METAL PURLINS UNKNOWN
	Planks	_ HEIRE FOREING ONIMONN
	Boards	
		12 (1/8" increments up to 1"; 32" increments
33	thereafter)	12 (2/0 Indiamond up to 1 / 1 Indiamond
34	DRAINAGE (check all):	
	ROOF EDGE	SCUPPERS INTERIOR GUTTERS
	GUTTERS &	SCUPPERS W/LEADER INTERIOR DRAINS
	DOWNSPOUTS	& DOWNSPOUTS
	DOWNSTOOLS	OVERFLOW SCUPPERS OTHER
40	UNDERLAYMENT	
41	TYPE(check all):	
		ASPHALT SATURATED OTHER
	UNKNOWN	SHEET NONE
	FULLY-ADHERED ICE	HIGH PERFORMANCE
	& WATER PROTECTION	NON-ASPHALT
	MEMBRANE	SLIP SHEET
50	ROOF COVERING	
51	TYPE (check one):	
	METAL PANEL - STANDING SEAM	
	GERTINIES GIR	METAL PANEL LAP SEAM
	SEPARATE CAP	ELAT COLDEDED CEAN
	Snap-on	FLAT SOLDERED SEAM
	Batten	METAL DANEL CUINCLE
	T-Style	METAL PANEL SHINGLE
	MECHANICALLY INTERLOCKED	OTHER
	Double lock seam	
	Single lock seam	
	INTEGRAL CAP	
	Snap lock	
	Integral batten	
	Integral standing seam	

52	BASE METAL: _ ZINC COATED STEEL	=	LEAD LEAD COATED COPPER UNKNOWN
53	PANEL FINISH: FACTORY APPLIED SMOOTH OTH FACTORY APPLIED STONE COATED NON MAINTENANCE COATING UNK		
54	PANEL ATTACHMENT: CONCEALED CLIPS OTHE EXPOSED FASTENERS IN PANELS	ΣR	
60	FLASHINGS		
61	TYPES (Record lineal feet of each): EAVE RAKE EDGE RIDGE CAP HIP CAP VALLEY HEADWALL TRANS. SIDEWALL TRANS. TYPES (Record lineal CONTINUOUS ROOF TO WALL TRANSITION INTERIOR GUTTERS FLEXIBLE BOOT FLANGED METAL		RAISED CURB
62	ACCESSORIES (check all): SNOW GUARDS WALKWAYS PHOTOVOLTAICS		LIGHTNING PROTECTION
63	OVERLAY:		
	IS ROOF OVERLAYED (Y/N/UNKNOWN) # OF LA	YERS	
70	REMARKS		

ACTNOV/INCTATIATION.

ROOF INSPECTION	ON WORKSHEET	AGENCI/INSTALLATIO						
BUILDING		LASHED PERIMETERURB FLASHINGS HRU PANEL FASTENERS_		DATE NAME				
Flash Fastener(FF) Flash Surf Det(FD) Panel Closure (PC) Eave F1 (EA) Rake Edge F1 (RE) Ridge Hip (CP) Valley F1 (VF)	Headwall Tran(HT) Sidewall Tran(ST) Roof to Wall (RW) Int Gutters (IG) Flex Boot (FB) Flanged Metal(FM) Ancillary Fl (AF) Flash Patch (FR)	Sec-Wide Det(SW) Loc Surf Det(SD) Panel Fasten(PF) Damage Panel(DP) Displ Panel (DL) Panel Patch (PA) Debris & Veg(DV) Equ Support (EQ)	Mech Int Seam (MS) Int Cap Seam (IC) Sep Cap Seam (SC) Lap Seam (LS) Tran Panel Lap(PL) Skylight Panel(SP)	ID #	DISTRESS	SEVERITY	DEFECT	QUANTITY
							- 1	
							- 1	
							- 10	150
				-			100	
					9 9		100	
							- 1	- 1
					1	NORTI	H	
SCALE:								(9)

	ROOF SECTION RATING FORM											
BUILDING SECTION							I	DATE		CALC.	BY	
FLAS CURB	HED PE FLASH	RIMETER FT	THRU F	ANEL I	FASTEN	ERS		_ A	AREASQ	FT	CHKD.	ВУ
		FLASHING						•	PANEL			
FD - PC - EA -	Flash Panel Eave F	DISTRESS TY ng Fastener HT - Surface Det ST - Closure RW - Tashing IG -	Headwall Sidewall Roof to N Built-in	Tran Wall T Gutte	ran		SD -	Local Panel	DISTRESS TYPES on Wide Det ized Surf Det MS -Me Fastener IC -In ed Panel SC -Se	tegra!	Cap S	Seam
RE -	Rake E Ridge	dge Flashing FB - Hip Flashing FM - Flashing AF - FR -	Flexible Flanged N Ancillary	Boot Metal/ y Flas	Curb		DL - DV -	Displ Panel Debri	aced Panel LS -La Patch PL -Tr s & Vegetation SP -Sk ment Support	p Sear an Par	n nel Lar	p
DIS	SEV	QUANTITIES	TOT	DEN	DA		DIS	SEV	QUANTITIES	TOT	DEN	DV
	0 0							3			10 10	
			-					100	-		. v	
			+					i d				
	8 8		- 2		. 3			2			1 22	
						1						
	2 2		89		8 1			8			8	
	0 0										10 52	
	-		-									
				1							2 2	
								8				
	8 8		-					8			8 8	
	2 0										0 0	
CORR	CORRECTED DEDUCT VALUE (CDV)					CORF	RECTE	D DEDUCT VALUE (CDV)				
		- CDV =							0 - CDV =		_%	

RCI CALCULATION	SHEET	AGENCY/I	AGENCY/INST.:					
DATE://	/ BLDG NO: SECTION ID: AREA: _							
ROOF SECTION	WITH METAL	PANEL ROO	OFING					
		VALUE	LOWEST	OTH	HER			
	PCI							
	FCI							
-			X 0.70	X 0	.30			
			(A)	(B)				
			(A+B)					
			RCI					
RATINGS								
14111100	86	5 - 100	EXCELLENT					
	7	1 - 85	VERY GOOD					
	5	6 - 70	GOOD					
	4	1 - 55	FAIR					
	2	6 - 40	POOR					
	1	1 - 25	VERY POOR					
	C	- 10	FAILED					

Flashing and Panel Distress Field Reference Card

	FLASHING DISTRESSES	FLASHING DISTRESSES (continued)						
Flashing Fasteners	FF M 1	missing or deteriorated flexible gasket, or fastener is corroded, improperly seated, or has a sealant repair but is watertight		AF L 1	curb/coping cap flashing is deformed with ponding at a location not adjacen to a lap or seam; or counterflashing is deformed			
	FF H 1	fastener or flexible gasket is loose, deteriorated or missing or enlarged hole; and allowing water to penetrate			elastomeric bellows expansion joint cover exists holes on a vertical surface			
Flash Surface Det	FD M 1 PC M 1	localized loss of finish or metal corrosion misaligned but watertight		AF M 2	unflashed or improperly flashed penetration passing through it but is watertight			
Panel Closure	PC M 2	pre-manufactured seam cap does not fit properly		AF H 1	holes or severe deterioration on a horizontal surface			
	PC H 1	non-metal panel closure is deformed, misaligned, damaged or missing;		AF H 2	missing or deformed; or ponding at a lap or seam			
	PC H 2	allowing water to penetrate metal panel closure is deformed, misaligned, or missing; allowing water to			displaced failed soldered joint, an open joint, a butt joint, or missing joint covers			
	8 St 5000C	penetrate		AF H 5	joints that are bucking water			
Eave Flashing	EA M 1	displaced but is watertight holes		AF H 6	sealant at reglet, top of counterflashing or sealed joint is missing or no longer functioning			
	EA H 2	non-cleated eave is displaced and allowing water to penetrate		AF H 7	counterflashing, exterior siding, or cladding does not extend over top of transition flashing			
	EA H 4	cleated eave is displaced or disengaged open joints or butt joints		AF H 8	curb/coping cap has unflashed or improperly flashed penetration passing			
	EA H 5			AF H S	through it that is allowing water to penetrate top of transition flashing is not properly counterflashed or terminated			
Palm Edge Flacking	RE M 1	loose or displaced but watertight and does not compromise panel securement	Flashing Patch		patch appears to be to be watertight and does not require a permanent			
	RE H 2	holes loose, displaced or missing and is allowing water to penetrate and/or		ED 14 4	repair			
Rake Edge Flashing		compromises panel securement		FR M 1	patch appears to be watertight and does require a more permanent repair			
	RE H 3	installed so that water is running against lap open joint or butt joints		FR H 1	patch is allowing water to penetrate			
		disengaged but is watertight	PANEL DISTRESSES					
	CP H 1			SW L 1	applied finish exhibits chalking, fading or scratching over the entire roof section, but no underlying corrosion			
Ridge Cap, Hip Cap	CP H 2	deformed or disengaged and allowing water to penetrate; or evidence of ponding at a lap or seam	Section-Wide	SW M 1	base metal or applied finish exhibits chalking, fading or scratching over the			
	CP H 3	missing	Surface Deterioration		entire roof section; requiring a coating or surface treatment			
	CP H 4	joints that are bucking water open joints or butt joints		SW H 1	base metal exhibits corrosion over the entire roof section; requiring a roof replacement			
	VF L 1	fastener is located in the valley but is watertight			localized loss of applied finish or localized metal corrosion			
	VF L 2 VF M 1	patch is watertight fastener has missing or deteriorated flexible gasket but watertight; or	Localized Surface	50 M 2	panel finish exhibits degradation caused by grease, solvent or oil drippings			
	NAME OF A	fastener is corroded, improperly seated, or temp repair fastener or flexible gasket is loose, deteriorated or missing and is allowing	Deterioration	SD H 1	for mech, interlocked seams, panel has corrosion holes; requiring localized			
Valley Flashing	VF H 1	water to penetrate; or fastener has an enlarged hole		SD H 2	repair panel finish exhibits degradation caused by grease, solvent or oil drippings			
	VF H 2	holes		DE 14.4	factorial to the second of the			
1	VF H 3	open joints or butt joint, or joints that are bucking water panel end that terminates in valley has become disengaged	Panel Fastener	PF M 1	fastener has missing or deteriorating flexible gasket or fastener is corroded, improperly seated, or has a sealant repair but is watertight			
	VF H 5	patch is allowing water to penetrate or is inappropriate	Defect	PF H 1	fastener, flexible gasket and/or metal washer is loose, deteriorated or			
	VF H 6 HT M 1			DP L 1	missing or has large hole around it allowing water to penetrate panel is dented, deformed, or kinked with no deformation of the seam, no			
Headwall Transition Flashing	HT H 1		Damaged Panel	50.14.4	loss of coating and no corrosion; and is watertight			
	HT H 2	disengaged or loose and allowing water to penetrate missing or deformed and allowing water to penetrate		DP M 1	panel is dented, deformed or kinked; allowing ponding water and/or corrosion			
		open joints or butt joints, or joints that are bucking water	Dalifaged Pariet	DP H 1	for mech, Interlocked panel system, panel has holes, splits or tears;			
Sidewall Transition				DP H 2	requiring localized repairs for non-mech interlocked systems, panel has holes, splits or tears that			
Flashing	ST H 2 ST H 3	disengaged or loose and is allowing water to penetrate open joints or butt joints, or joints that are bucking water		DL H 1	require panel replacement panel is loose or displaced, requiring repositioning and re-securement			
,		missing or deformed and is allowing water to penetrate	Displaced Panel	DL H 2	panel is missing and requires replacement			
		rated low-severity as a minimum loose, deformed or missing seam cover		PA L 1	patch appears to be watertight and does not require a more permanent repair			
Train and Harshor	IG L 1	gutter is lined with elastomeric membrane or coating and is watertight	Panel Patch	PA M 1	patch appears to be watertight and requires a more permanent repair			
	IG M 1	gutter is not lined with elastomeric membrane or coating and is watertight		PA H 1	patch is allowing water to penetrate			
Built-in Gutters	IG H 1	Interior gutter is not lined with elastomeric membrane or coating and has	Debris and		collection of foreign objects or vegetation or grease, solvent or oil drippings			
Dani-III Cattors	IG H 2	holes, splits or open joints gutter having elastomeric membrane or coating has holes splits or open	Vegetation	DV M 2	on the roof which cause no degradation tree branches making contact with the roofing system			
		joints		EQ L 1	rated low severity as a minimum			
	IG H 3 FB L 1	gutter or drain is clogged rated low-severity as a minimum		EQ M 1	support is bolted or fastened through the metal panel seam flashing and the bolt(s) are watertight			
	FB M 1	loose, missing, corroded or misaligned drawband	Improper Equipment	EQ M 2	support has caused damage to surrounding panels but is watertight			
Flexible Boot	FB H 1	boot is missing or has holes; or interferes with a panel seam and allowing water to penetrate	Support	EQ H 1	support is bolted or fastened through the metal panel seams or flashing and allowing water to penetrate			
Flashings	FB H 2	deformed securement ring that is allowing water to penetrate		EQ H 2	support has caused damage to surrounding panels and is allowing water to			
	FB H 3	failed or missing sealant around the drawband allowing water to penetrate	Mechanically	MS L 1	penetrate seam is deformed or flattened but still engaged and is watertight			
		rated low-severity as a minimum	Interlocked Seam		seam is open or allowing water to penetrate; or seam is disengaged			
	FM M 1	flange on upslope side is mounted on top of panel, bucking water, but is watertight	Integral Cap Seam		seam is deformed or flattened but still engaged and is watertight seam is disengaged; requiring localized repair			
	FM M 2	flange on downslope side is mounted below panel, bucking water, but is	Defect		seam is disengaged due to panel deformity, requiring panel replacement			
	FM M 3	watertight sealant around umbrella is deteriorating, torn, or deformed; but is watertight		SC L 1	seam is deformed or flattened but still engaged, and is watertight			
	6 2000000		Separate Cap Seam	SC H 1	seam is disengaged; requiring localized repair			
Flanged Metal and	FM H 1	flashing impedes drainage holes	Defect		seam is damaged or missing, requiring cap replacement panel is damaged at seam location; requiring panel and cap replacement			
Raised Curb Flashing	FM H 3	joint has failed and is allowing water to penetrate						
	FM H 4	flange on upslope side is mounted on top of panel and allowing water to penetrate	Lap Seam Defect		seam is open with no panel deformity; requiring localized repair seam is open due to panel deformity; requiring panel replacement			
	FM H 5	flange on downslope side is mounted below panel and is allowing water to penetrate	Transverse Panel	PL M 1	for cleated end lap, panel is disengaged from cleat			
	FM H 6	penetrate missing seam closure on downslope side	Lap Defect		end lap joint between panels has failed sealant or open fishmouths panel lap is bucking water			
	FM H 7	flange is open or unsealed		SP L 1	rated low severity as a minimum			
		top of pipe flashing is open sealant around umbrella is missing or is allowing water to penetrate	Integrated Skylight		composite material exhibits visible fibers, significant discoloration or other signs of degradation			
			Panel Defect	SP H 1	joint between skylight panel and adjacent metal panel is not watertight or			
				SDI LI 1	bucking water holes, splits or tears; allowing water to penetrate			
				SF II Z	nores, spins or realis, allowing water to penetrate			

REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing this collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number. PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ADDRESS.

or intermedient in it decerned diopidy a currently raina	0.11.2 0.01.11.01.11.01.11.11.11.11.11.11.11.11	, , _ , , , , , , , , , , , , , , , , ,
1. REPORT DATE (DD-MM-YYYY)	2. REPORT TYPE	3. DATES COVERED (From - To)
December 2012	Final	
4. TITLE AND SUBTITLE	5a. CONTRACT NUMBER	
ROOFER Inventory Procedure		
·	-	5b. GRANT NUMBER
		5c. PROGRAM ELEMENT NUMBER
6. AUTHOR(S)	5d. PROJECT NUMBER	
David M. Bailey, Joseph E. Ka		
•		5e. TASK NUMBER
		5f. WORK UNIT NUMBER
7. PERFORMING ORGANIZATION N	8. PERFORMING ORGANIZATION REPORT	
US Army Engineer Research as	nd Development Center	NUMBER
Construction Engineering Rese	*	ERDC TR-12-15
P.O. Box 9005	aren Bassiatory	
Champaign, IL 61826-9005		
1 · 6 ,		
0 SPONSODING / MONITODING AG	ENCY NAME(S) AND ADDRESS(ES)	10. SPONSOR/MONITOR'S ACRONYM(S)
	. ,	
Office of the Assistant Chief of	ACSIM	
Facilities Branch (DAIM-ODF	11. SPONSOR/MONITOR'S REPORT	
2511 Jefferson Davis Highway	NUMBER(S)	
Arlington, VA 22202		
12. DISTRIBUTION / AVAILABILITY	STATEMENT	L

Approved for public release; distribution is unlimited.

13. SUPPLEMENTARY NOTES

14. ABSTRACT

The US Army is responsible for maintaining millions of square feet of metal panel roofing on a wide variety of facilities. This type of roofing system shares a number of general characteristics with other types, but they use certain distinct types of materials that have their own specialized distress and degradation mechanisms.

Dedicated inspection guidance and condition index calculation methods are needed to quantify the condition of an installation's metal panel roofing assets in order to make the best use of Army maintenance and repair resources. This manual was developed to serve as a standard reference for performing inspections and calculating a flashing condition index (FCI) and panel condition index (PCI) for use in facility maintenance management activities. This guidance represents a new implementation of the widely used ROOFER Sustainment Management System.

15. SUBJECT TERMS

facilities, inspection, ROOFER, maintenance and repair (M&R), metal panel roofing, Sustainment Management Systems (SMS)

16. SECURITY CL	ASSIFICATION OF:		17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON
a. REPORT	b. ABSTRACT	c. THIS PAGE			19b. TELEPHONE NUMBER (include area code)
Unclassified	Unclassified	Unclassified		132	